


Add to my favorites / bookmarks 🧝 📱 🛛 Print this page 🚎

Parts for Mercury Marine 7.5 HP FLYWHEEL AND IGNITION COIL

Revise Search: <u>Start Over</u> > <u>Different Engine Model</u> > <u>Different Serial Number Range</u> > <u>Different Component</u> YOU ARE HERE: MERCURY > 7.5 HP > 3801458 THRU 4851692 (USA) > FLYWHEEL AND IGNITION COIL « <u>Previous</u> | <u>Next</u> »

Reference numbers in this diagram can be found in a light blue row below — scroll down to order. Each product listed is an <u>OEM</u> or <u>aftermarket</u> equivalent part. [<u>Example</u>]



Reference numbers in this diagram can be found in a light blue row below — scroll down to order. Each product listed is an <u>OEM</u> or <u>aftermarket</u> equivalent part. [<u>Example</u>]

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order			
#1	245-5277A 1	FLYWHEEL ASSEMBLY (1 required per assembly) UNITED STATES 3801458 THRU 3929194 AUSTRALIA 8015315 THRU 8019089 BELGIUM 9043194 THRU 9059653 CANADA 7028598 THRU 7036397							
No Image Available Rentreparen	245-5277А 1 ОЕМ	245-5277A 1 - Flywheel Assembly, NLA (more info)	MERCURY QUICKSILVER	\$235.00	\$235.00	1 in stock.			
#1	245-5277A 3	FLYWHEEL ASSEMBLY (1 required p UNITED STATES 3929195 THRU 43 9059654 THRU 9115164 CANADA 7	97536 AUSTRAL		HRU 803844	9 BELGIUM			

Ref. No.		Part No.	Description	Manufacturer	List Price	Your Price	Order			
No Image Available		245-5277A 3	FLYWHEEL ASSY O NLA (more info)				Unavailable (
#1		251-6194A 1	FLYWHEEL ASSEMBLY (1 required per assembly) UNITED STATES 4397537 AND UP AUSTRALIA 8038450 AND UP CANADA 7076123 AND UP							
No Image Available		251-6194A Replaced by 1	FLYWHEEL O - Replaced by 251-6105A 1 (more info)				Unavailable (
No Image Available References		251-6105А 1 оем	251-6105A 1 - Flywheel, NLA (more info)	WERCURY QUICKSILVER	\$125.00	\$125.00	2 in stock.			
#1		251-6105A 1	FLYWHEEL ASSEMBLY (ELECTRIC)	(1 required per	assembly)					
No Image Available		251-6105А 1 оем	251-6105A 1 - Flywheel, NLA (more info)	MERCURY QUICKSILVER	\$125.00	\$125.00	2 in stock.			
#1		251-6105A 3	FLYWHEEL ASSEMBLY (1 required BELGIUM 9115165 AND UP	per assembly)						
No Image Available		251-6105A Replaced by 3	FLYWHEEL O - Replaced by 251-6105A 1 (more info)				Unavailable (
No Image Available		251-6105A 1 OEM	251-6105A 1 - Flywheel, NLA (more info)	MERCURY QUICKSILVER	\$125.00	\$125.00	2 in stock.			
#2		28-20094	KEY, FLYWHEEL DRIVE (1 required	l per assembly)						
No Image Available		28-20094 OEM	28-20094 - Key - Priced individually (more info)	QUICKSILVER	\$1.40	\$1.40	6 in stock.			
#3		12-36245	WASHER, FLYWHEEL NUT (1 requi	red per assembl	y)					
No Image Available		12-36245	WASHER O NLA (more info)				Unavailable (
#4		11-20696	NUT, FLYWHEEL (1 required per as	ssembly)						
Ó	€	11-20696 ОЕМ	11-20696 - Nut, NLA (more info)	QUICKSILVER	\$5.00	\$5.00	ADD TO CART			
#5		339-5288A 1	COIL ASSEMBLY, IGNITION (2 req UNITED STATES 3801458 THRU 41 9043194 THRU 9079488 CANADA	31609 AUSTRAI	LIA 8015315 T	HRU 802883	9 BELGIUM			
No Image Available References		339-5288A Replaced by 1	COIL O - Replaced by 339-5748A 2 (more info)				Unavailable (
No Image Available Brandrage com		339-5748A Replaced by 2	COIL ASSY O - Replaced by 339-5288A 2 (more info)				Unavailable (
No Image Available Reterfactor con		339-5288A Replaced by 2	COIL O - Replaced by 339-5288T 2 (more info)				Unavailable (
	⊕ `	339-5288Т 2 ОЕМ	<u>339-5288T 2 - Coil</u> (more info)	MERCURY QUICKSILVER	\$107.00	\$91.63	ADD TO CART			
#5		339-5288A 2	COIL ASSEMBLY, IGNITION (2 req UNITED STATES 4131610 THRU 43 9079489 THRU 9102613 CANADA	14384 AUSTRAI	LIA 8028840 T	HRU 803556	9 BELGIUM			
No Image Available		339-5288A Replaced by 2	COIL O - Replaced by 339-5288T 2 (more info)				Unavailable (
	⊕ ,	339-5288Т 2 ОЕМ	<u>339-5288T 2 - Coil</u> (more info)	MERCURY QUICK SILVER	\$107.00	\$91.63	ADD TO CART			

Ref. No.		Part No.	Description	Manufacturer	List Price	Your Price	Order	
#5		339-5748A 2	COIL ASSEMBLY, IGNITION (2 req UNITED STATES 4314385 AND UP CANADA 7065473 AND UP			BELGIUM 91(02614 AND	U
No Image Available		339-5748A Replaced by 2	COIL ASSY O - Replaced by 339-5288A 2 (more info)				Unavailable	(
No Image Available		339-5288A Replaced by 2	COIL O - Replaced by 339-5288T 2 (more info)				Unavailable	į
	⊕ ,	339-5288Т 2 ОЕМ	339-5288T 2 - Coil (more info)	WERCURY QUICK SILVER	\$107.00	\$91.63	ADD TO CAP 10+ in stock.	R
6		13-26996	LOCKWASHER, IGNITION COIL TE	RMINAL (4 requ	ired per assem	ibly)		
No Image Available Renetation		13-26996 ОЕМ	<u>13-26996 - Lockwasher - Priced</u> Individually (more info)	MERCURY QUICK SILVER	\$0.80	\$0.80	ADD TO CAP	R
7		11-45076	NUT, IGNITION COIL TERMINAL (4	I required per as	ssembly)			
No Image Available		11-45076 ОЕМ	<u>11-45076 - Nut - Priced Individually</u> (more info)	QUICK SILVER	\$1.20	\$1.20	ADD TO CAP	R
8		66355	COVER, IGNITION COIL (2 require	d per assembly)				
	⊕ `	66355 OEM	66355 - Cover, NLA (more info)	QUICKSILVER	\$13.75	\$13.75	ADD TO CAP	R
9		10-72074	SCREW, COIL COVER TO REAR SUP	PORT BRACKET	(4 5/8") (3 re	quired per as	ssembly)	
No Image Available References		10-72074	SCREW O NLA (more info)				Unavailable	
10		11-20110	NUT, COIL COVER SCREW (3 requi	red per assembl	y)			
9	⊕ `	11-20110 ОЕМ	<u>11-20110 - Nut - Priced individually</u> (more info)	QUICKSILVER	\$1.20	\$1.20	ADD TO CAP	R
11		84-63212A 2	LEAD ASSEMBLY, HIGH TENSION (2 required per a	issembly)			
No Image Available		84-63212A Replaced by 2	WIRE ASSY O - Replaced by 84-90816A25 (more info)				Unavailable	
No Image Available Reministration		84-90816A25 Replaced by	WIRE ASSY @2 O - Replaced by 84-93475A25 (more info)				Unavailable	
No Image Available Rendance		84-93475A25 Replaced by	WIRE ASSY O - Replaced by 84-99215A25 (more info)				Unavailable	
No Image Available		84-99215A25 Replaced by	WIRE ASSY O - Replaced by 84-813715A 1 (more info)				Unavailable	
	⊕ `	84-813715A 1 OEM	84-813715A 1 - Ignition Cable Assembly (more info)	MERCURY QUICK SILVER	\$25.00	\$21.41	ADD TO CAP	R
-	Ð,	18-5228-1 Aftermarket	18-5228-1 - Spark Plug Wire, 84-813715A1 (more info)	Sierra	\$24.40	\$17.31	ADD TO CAP 10+ in stock.	R
	⊕ ,	18-5227-1 Aftermarket	18-5227-1 - Spark Plug Wire, 9 inch Pre-made (more info)	Sierra	\$24.40	\$17.31	ADD TO CAP	R

Ref. No.		Part No.	Description	Manufacturer	List Price	Your Price	Order	
No Image Available		332-2854 Replaced by	BOOT @3 O - Replaced by 332-2854T01 (more info)				Unavailable	?
No Image Available Restaures		332-2854T01 ОЕМ	<u>332-2854T01 - BOOT - Priced</u> Individually (more info)	PERCURY DUICK SILVER	\$1.90	\$1.90	Available to order: Usually ships within 8 days	1
#13		85-71006A 1	PROTECTOR ASSEMBLY, SPARK PL	UG (2 required	per assembly)			
No Image Available		85-71006A Replaced by 1	PRTCTOR ASSY@10 O - Replaced by 85-63709A 1 (more info)				Unavailable	?
	⊕ `	85-63709А 1 ОЕМ	85-63709A 1 - Boot Kit - Black - Priced Individually (more info)	QUICKSILVER	\$5.60	\$5.60	ADD TO CART 10+ in stock.	т (?
#14		33-59599	SPARK PLUG (CHAMPION L-77V) (UNITED STATES 3801458 THRU 41 9043194 THRU 9079488 CANADA 3	31609 AUSTRA	LIA 8015315 TI	HRU 802883	9 BELGIUM	
No Image Available		33-59599 Replaced by	SPARK PLUG @10 O - Replaced by 33-57451 (more info)				Unavailable	?
No Image Available		33-57451 Replaced by	SPARK PLUG @8 O - Replaced by 33-97180 (more info)				Unavailable	(?
A	Ð,	33-97180 Replaced by	NGK BUHW @10 O - Replaced by 33-97180Q (more info)				Unavailable	(?
No.	⊕ ,	33-97180Q OEM	33-97180Q - NGK Buhw - Priced individually (more info)	MERCURY QUICKSILVER	\$5.42	\$5.42	Available to order: Usually ships within 8 days	т (?
	⊕ `	BUHW Aftermarket	BUHW - NGK Plug, 2622 (more info) Replaces OEM #0503701	NGK	\$2.79	\$2.79	ADD TO CART 10+ in stock.	т (?
8	⊕ `	BUH Aftermarket	BUH - NGK Plug, 2422 (more info)	NGK	\$2.69	\$2.69	2 in stock.	т (?
	⊕ ,	L76V Aftermarket	L76V - Champion Spark Plug (#827M) (more info) Replaces OEM #0384751	CHAMPION	\$3.09	\$3.09	ADD TO CART 10+ in stock.	т (?
#14		33-58194	SPARK PLUG (AC V40FFK) (2 requi UNITED STATES 4131610 AND UP CANADA 7050208 AND UP			BELGIUM 90	79489 AND L	UF
No Image Available		33-58194 Replaced by	SPARK PLUG @8 O - Replaced by 33-97182 (more info)				Unavailable	?
	Ð,	33-97182 Replaced by	<u>NGK BUHW-2 @10 O - Replaced by</u> <u>33-97182Q</u> (more info)				Unavailable	0
1	⊕ `	33-97182Q OEM	33-97182Q - NGK BUHW-2 - Priced individually (more info)	PERCURY DUICK SILVER	\$5.42	\$5.42	Available to order: Usually ships within 8 days	a (
	⊕ `	BUHW-2 Aftermarket	BUHW-2 - NGK Plug, 5626 (more info) Replaces OEM #0503702	NGK@	\$2.79	\$2.79	ADD TO CART	т (?

