

## Section 5

# DF9.9B/15A/20A (310001 and later)

### ***FOREWORD***

*This supplement describes the technical data and servicing procedures for the following models:*

**DF9.9B/BE/BR (00995F-310001 and later)**

**DF15A/AE/AR (01504F-310001 and later)**

**DF20A/AE/AR (02002F-310001 and later)**

This supplement describes only service information which differs from the main manual. Whenever servicing the above models, consult this supplement first. For any section, item or description not found in this supplement, refer to Section 00 through Section 4.

# IMPORTANT NOTICE

## WARNING / CAUTION / NOTICE / NOTE

Please read this manual and follow its instructions carefully. To emphasize special information, the symbol and the words **⚠ WARNING**, **⚠ CAUTION**, **NOTICE** and **NOTE** have special meanings. Pay special attention to the messages highlighted by these signal words.

### **⚠ WARNING**

---

Indicates a potential hazard that could result in death or serious injury.

---

### **⚠ CAUTION**

---

Indicates a potential hazard that could result in minor or moderate injury.

---

### **NOTICE**

---

Indicates a potential hazard that could result in damage to the motor or boat.

---

### **NOTE**

---

Indicates special information to make maintenance easier or instructions clearer.

---

Please note, however, that the warnings and cautions contained in this manual cannot possibly cover all potential hazards relating to the servicing, or lack of servicing, of the outboard motor. In addition to the **⚠ WARNING**, **⚠ CAUTION**, and **NOTICE** stated, you must also use good judgment and observe basic mechanical safety principles.

### **⚠ WARNING**

---

This service manual is intended for authorized Suzuki outboard motor dealers and qualified service technicians only.

Apprentice mechanics or do-it-yourself mechanics that don't have the proper tools and equipment may not be able to properly perform the services described in this manual. Improper repair may result in injury to the mechanic and may render the engine unsafe for the boat operator and passengers.

---