

Add to my favorites / bookmarks 🙀 📗 Print this page


Parts for Mercury Marine 7.5 HP DRIVE SHAFT HOUSING ASSEMBLY

Revise Search: Start Over > Different Engine Model > Different Serial Number Range > Different Component

YOU ARE HERE: MERCURY > 7.5 HP > 3801458 THRU 4851692 (USA) > DRIVE SHAFT HOUSING ASSEMBLY

« Previous | Next »

Reference numbers in this diagram can be found in a light blue row below — scroll down to order. Each product listed is an <u>QEM</u> or <u>aftermarket</u> equivalent part. [<u>Example</u>]



Reference numbers in this diagram can be found in a light blue row below — scroll down to order. Each product listed is an <u>OEM</u> or <u>aftermarket</u> equivalent part. [<u>Example</u>]

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
#1	1556-4901A 2	DRIVE SHAFT HOUSING ASSEMBL' UNITED STATES 3801458 THRU 43 9043194 THRU 9102613 CANADA	314384 AUSTRA	ĹIÀ 8015315		
No Image Available	1556-4901A 2 Replaced by	DRIVE SHAFT HSG O - Replaced by 1556-5945A 2 (more info)				Unavailable 🗿
No Image Available	1556-5945A 2 Replaced by	DRIVE SHAFT HSG O - Replaced by 1556-8451A 1 (more info)				Unavailable 👩

ef. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order	
No Image Available	1556-8451A 1 OEM	1556-8451A 1 - Drive Shaft Housing, NLA (more info)	MERCURY QUICKSILVER	\$220.00	\$220.00	1 in stock.	RT
l	1558-4902A 2	DRIVE SHAFT HOUSING ASSEMBLY UNITED STATES 3801458 THRU 43 9043194 THRU 9102613 CANADA 7	14384 AUSTRÁI	LIA 8015315		•	М
No Image Available	1558-4902A 2	DRIVE SHAFT HSG O NLA (more info)				Unavailable	
2	16-66373	STUD, DRIVE SHAFT HOUSING TO C UNITED STATES 3801458 THRU 43 9043194 THRU 9102613 CANADA 7	14384 AUSTRA	LÌA 8015315		• ,	
No Image Available	16-66373	STUD O NLA (more info)				Unavailable	:
1	1556-5945A 2	DRIVE SHAFT HOUSING ASSEMBLY UNITED STATES 4314385 AND UP UP CANADA 7065473 AND UP					D
No Image Available	1556-5945A 2 Replaced by	DRIVE SHAFT HSG O - Replaced by 1556-8451A 1 (more info)				Unavailable	:
No Image Available	1556-8451A 1 OEM	1556-8451A 1 - Drive Shaft Housing, NLA (more info)	MERCURY QUICK SILVER	\$220.00	\$220.00	1 in stock.	R
L	1558-5946A 3	DRIVE SHAFT HOUSING ASSEMBLY UNITED STATES 4314385 AND UP UP CANADA 7065473 AND UP					D
No Image Available	1558-5946A 3 Replaced by	DRIVE SHAFT HSG O - Replaced by 1558-8453A 1 (more info)				Unavailable	
No Image Available	1558-8453A 1	DRIVE SHAFT HSG O NLA (more info)				Unavailable	
3	11-34863	NUT, DRIVE SHAFT HOUSING STUD	(3/8 - 24) (1 ו	equired per a	ssembly)		
No Image Available	11-34863 Replaced by	NUT @3 O - Replaced by 11-826709113 (more info)				Unavailable	:
	11-826709113 OEM	11-826709113 - Nut -ss - Priced Individually (more info)	PERCURY	\$5.00	\$5.00	9 in stock.	R
4	11-35814	NUT, GEAR HOUSING TO DRIVE SH	AFT HOUSING S	STUD (5/16 -	14) (1 requi	red per	
No Image Available	11-35814 Replaced by	NUT @5 O - Replaced by 11-826709 11 (more info)				Unavailable	
	⊕ 11-826709 11 OEM	11-826709 11 - Nut - Priced individually (more info)	MERCURY QUICKSILVER	\$3.60	\$3.60	Available to order: Usually ships within 8 days	P
5	65518	COVER, TRIM - DRIVE SHAFT HOUS UNITED STATES 3801458 THRU 41 9043194 THRU 9079488 CANADA 7	31609 AUSTRAI	LIA 8015315		39 BELGIUN	М
No Image Available	65518 Replaced by	COVER O - Replaced by -72471 (more info)				Unavailable	
No Image Available	72471 OEM	72471 - Over, NLA (more info)	MERCURY QUICK SILVER	\$24.00	\$24.00	2 in stock.	R
5	72471	COVER, TRIM - DRIVE SHAFT HOUS UNITED STATES 4131610 AND UP				070480 AND	_

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
No Image Available Memotropicous	72471 OEM	72471 - Over, NLA (more info)	MERCURY	\$24.00	\$24.00	2 in stock.
#6	10-64652	SCREW, TRIM COVER TO BOTTOM C	OWL (1/2") (4	required per a	assembly)	
No Image Available	10-64652 OEM	10-64652 - Screw, NLA (more info)	MERCURY	\$1.35	\$1.35	7 in stock.
#7	32-34395A 1	HOSE, TELL TALE (9 1/2") (1 requir	red per assemb	oly)		
No Image Available	32-34395A 1 Replaced by	HOSE ASSY O - Replaced by 32-99127109 (more info)				Unavailable 👩
No Image Available	32-99127109 Replaced by	TUBING-57 INCH O - Replaced by 32-830756109 (more info)				Unavailable 🗿
Q	32-830756109 Replaced by	HOSE-57 INCH O - Replaced by 32-8M0047428 (more info)				Unavailable 🗿
0	32-8M0047428 OEM	32-8M0047428 - Hose -57 INCH (more info)	MERCURY	\$43.90	\$37.59	ADD TO CART 1 in stock.
#8	32-39061	TUBE, WATER OUTLET(SHORT SHAI	FT) (1 required	per assembly)		
™ •	32-39061	TUBING O (more info)				Unavailable 🔞
#8	32-39062	TUBE, WATER OUTLET(LONG SHAFT	Γ) (1 required p	er assembly)		
No Image Available	32-39062	TUBING O NLA (more info)				Unavailable 🗿
#9	10-28634	SCREW, FLUSH - DRIVE SHAFT HOU	ISING (1 requir	ed per assemb	oly)	
○ ♥	10-28634 Replaced by	SCREW @5 O - Replaced by 10-79953 (more info)				Unavailable (3)
○ ୭ •	10-79953 Replaced by	SCREW @5 O - Replaced by 10-79953A 2 (more info)				Unavailable 🗿
≜ ○ •	10-79953A 2 Replaced by	SCREW KIT-DRAIN O - Replaced by 10-79953Q 2 (more info)				Unavailable 🗿
♣ ○ •	10-79953Q 2 Replaced by	SCREW KIT @2 O - Replaced by 10-79953Q04 (more info)				Unavailable 🗿
0 • •	10-79953Q04 OEM	10-79953Q04 - Screw Kit - Priced Individually (more info)	MERCURY	\$5.60	\$5.60	ADD TO CART 10+ in stock.
0 ♥ €	18-2244 Aftermarket	<u>18-2244 - Plug Kit, 10-79953A2</u> (more info)	Sierra	\$2.91	\$1.95	ADD TO CART 10+ in stock.
0 • •	10-79953K04 OEM	10-79953K04 - Screw - Drain - Priced Individually (more info)	PERCURY	\$5.60	\$5.60	7 in stock.
#10	12-20260	WASHER, SEALING - FLUSH SCREW	(1 required pe	r assembly)		
0	12-20260 Replaced by	WASHER @15 O - Replaced by 12-19183 (more info)				Unavailable 👩
0	12-19183 Replaced by	WASHER-BLK @15 O - Replaced by 12-19183 2 (more info)				Unavailable 🗿
	12-19183 2	WASHER-ORAN @15 O - Replaced by 12-19183 3				Unavailable 🗿

Ref. No.		Part No.	Description	Manufacturer	List Price	Your Price	Order
0	⊕ ,	Replaced by	(more info)				
0	⊕ ູ	12-19183 3 OEM	12-19183 3 - Seal -blue - Priced Individually (more info)	MERCURY	\$0.94	\$0.94	ADD TO CART 10+ in stock.
0	⊕,	18-2945-9 Aftermarket	<u>18-2945-9 - Gasket 12-19183 2-Pack</u> (more info) Replaces OEM #0307552	Sierra	\$2.50	\$1.48	ADD TO CART 10+ in stock.
#11		27-39050	GASKET, ADAPTOR PLATE TO DRIV	E SHAFT HOUS	NG (1 require	d per assem	bly)
	⊕ ,	27-39050 OEM	27-39050 - Gasket - Priced individually (more info)	PERCURY QUICKSILVER	\$5.90	\$5.90	ADD TO CART 10+ in stock.
#12		11-24652	NUT, DRIVE SHAFT HOUSING TO PO	OWERHEAD STU	JDS (4 require	d per assem	bly)
8	⊕,	11-24652 OEM	11-24652 - Nut - Priced individually (more info)	MERCURY	\$1.20	\$1.20	10+ in stock.
#13		47259A 1	BLOCK ASSEMBLY, DRIVE SHAFT LO	ONG SHAFT (1 r	equired per a	ssembly)	
No Image Available		47259A 1	47259A 1 - Block Assembly, NLA (more info)	MERCURY	\$7.50	\$7.50	9 in stock.
#14		10-47225	SCREW, BLOCK TO DRIVE SHAFT H	SG. (1 1/4") LC	NG SHAFT (2	required pe	assembly)
No Image Available		10-47225 OEM	10-47225 - Screw, NLA (more info)	MERCURY	\$1.25	\$1.25	ADD TO CART 10+ in stock.
#15		1559-4917	SADDLE (1 required per assembly) UNITED STATES 3801458 THRU 43: 9043194 THRU 9102613 CANADA 7			THRU 80355	69 BELGIUM
No Image Available		1559-4917 Replaced by	SADDLE O - Replaced by 1559-5968 (more info)				Unavailable 🗿
No Image Available		1559-5968 Replaced by	SADDLE O - Replaced by 1559-5968A 1 (more info)				Unavailable 👩
No Image Available		1559-5968A 1 Replaced by	SADDLE ASSY O - Replaced by 1559-6678A 1 (more info)				Unavailable 🗿
No Image Available		1559-6678A 1 Replaced by	SADDLE O - Replaced by 1559-7538A 1 (more info)				Unavailable 👩
No Image Available		1559-7538A 1 Replaced by	SADDLE ASSY O - Replaced by 1559-8448A 2 (more info)				Unavailable 🗿
No Image Available		1559-8448A 2	SADDLE O NLA (more info)				Unavailable 🗿
#15		1559-5968A 1	SADDLE ASSEMBLY (1 required per UNITED STATES 4314385 AND UP UP CANADA 7065473 AND UP		35570 AND UP	BELGIUM 9:	102614 AND
No Image Available		1559-5968A 1 Replaced by	SADDLE ASSY O - Replaced by 1559-6678A 1 (more info)				Unavailable 🗿
No Image Available		1559-6678A 1 Replaced by	SADDLE O - Replaced by 1559-7538A 1 (more info)				Unavailable 👩
No Image Available		1559-7538A 1 Replaced by	SADDLE ASSY O - Replaced by 1559-8448A 2 (more info)				Unavailable 👩

Ref. No.		Part No.	Description	Manufacturer	List Price	Your Price	Order
No Image Available		1559-8448A 2	SADDLE O NLA (more info)				Unavailable 🗿
#16		64076	BUMPER, THRUST - SADDLE (1 requ	iired per assem	ibly)		
No Image Available		64076 OEM	64076 - Bumper, NLA (more info)	MERCURY	\$3.00	\$3.00	3 in stock.
#17		30646A 2	MOUNT ASSEMBLY (LOWER AND UPFOR MERC 110L LONG SHAFT ENGI (A-30646A2) WITH 2 A-30646A3				LIES
No Image Available		30646A 2 Replaced by	MOUNT ASSY @3 O - Replaced by -77754 (more info)				Unavailable 👩
No Image Available		77754 Replaced by	MOUNT @2 O - Replaced by -79896A 1 (more info)				Unavailable 👩
9	⊕,	79896A 1	MOUNT ASSY O NLA (more info)				Unavailable 👩
#18		53-26406	RING, RETAINING - UPPER AND LO	WER MOUNT (4	required per	assembly)	
No Image Available		53-26406 OEM	53-26406 - Snap Ring - Priced individually (more info)	MERCURY QUICKSILVER	\$2.50	\$2.50	5 in stock.
C	⊕_	994-6406 Aftermarket	994-6406 - Retainer (snap Ring) (more info)	EDI Hectronics	\$5.99	\$3.92	1 in stock.
#19		53041	COVER, LOWER MOUNT (2 required UNITED STATES 3801458 THRU 41: 9043194 THRU 9079488 CANADA 7	31609 AUSTRÁI		THRU 80288	39 BELGIUM
No Image Available		53041 Replaced by	COVER O - Replaced by -71490 (more info)				Unavailable 🔞
No Image Available		71490 OEM	71490 - Cover, NLA (more info)	MERCURY	\$9.00	\$9.00	ADD TO CART 10+ in stock.
#19		71490	COVER, LOWER MOUNT (2 required UNITED STATES 4131610 AND UP A UP CANADA 7050208 AND UP		8840 AND UP	BELGIUM 9	079489 AND
No Image Available		71490 OEM	71490 - Cover, NLA (more info)	MERCURY	\$9.00	\$9.00	ADD TO CART 10+ in stock.
#20		10-45817	SCREW, LOWER MOUNT COVER TO	MOUNT (7/16")) (2 required	per assembl	y)
©	⊕ ,	10-45817 OEM	10-45817 - Screw - Priced individually (more info)	MERCURY QUICKSILVER	\$1.25	\$1.25	ADD TO CART 10+ in stock.
#21		71057	LINK ROD, REVERSE LOCK (1 requir UNITED STATES 3801458 THRU 41: 9043194 THRU 9079488 CANADA 7	31609 AUSTRAI	LÍÁ 8015315	THRU 80288	39 BELGIUM
	••⊕	71057	ROD O NLA (more info)				Unavailable 🗿
#22		10-65414	SCREW, CAM RETAINER TO DRIVE	SHAFT HOUSING	G (3/4") (2 re	equired per a	assembly)
No Image Available		10-65414 OEM	10-65414 - Screw, NLA (more info)	MERCURY QUICKSILVER	\$1.35	\$1.35	ADD TO CART 10+ in stock.
#23		65216	CAM, REVERSE LOCK (1 required pe	er assembly)			
Acres (1)	⊕(65216	CAM O NLA (more info)				Unavailable 🗿

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
#24	61008	RETAINER, REVERSE LOCK CAM UNITED STATES 3801458 THRU 9043194 THRU 9079488 CANAI	4131609 AUSTRA	LIA 8015315	THRU 80288	39 BELGIUM
No Image Available	61008 Replaced by	GUIDE O - Replaced by -72007 (more info)				Unavailable
6 €	72007 OEM	72007 - Guide, NLA (more info)	PERCURY QUICK SILVER	\$8.00	\$8.00	ADD TO CAR
#24	72007	RETAINER, REVERSE LOCK CAM UNITED STATES 4131610 AND UP CANADA 7050208 AND UP	• •	• ,	BELGIUM 9	079489 AND
€	72007 OEM	72007 - Guide, NLA (more info)	MERCURY QUICK SILVER	\$8.00	\$8.00	ADD TO CAR



Subscribe to the MarineEngine.com Newsletter

Periodically we'll send you Tech Tips, How-To's and Boating Information. Just enter your e-mail address and click Subscribe!

email address Subscribe

You can easily unsubscribe from the newsletter at any time.

🔀 Why Us & Reviews 🛛 Boat Repair Forum 🔼 Video Gallery

HOME | CONTACT | SHIPPING | RETURNS | CART

Boat Engine PartsBoat Motor ManualsBoat Accessories

About Us | Terms of Use | Privacy Policy

© 2015 MarineEngine.com, Inc. All rights reserved.

MarineEngine.com, 184 Jones Drive, Brandon, VT 05733 USA Phone: 802-247-4700 | Fax: 802-419-3055 | eMail: info@marineengine.com

7/18/2015 11:36 PM 6 of 6