


Parts for Mercury Marine 7.5 HP GEAR HOUSING ASSEMBLY, COMPLETE

Revise Search: Start Over > Different Engine Model > Different Serial Number Range > Different Component

YOU ARE HERE: MERCURY > 7.5 HP > 3801458 THRU 4851692 (USA) > GEAR HOUSING ASSEMBLY, COMPLETE

« Previous | Next »

Reference numbers in this diagram can be found in a light blue row below — scroll down to order. Each product listed is an <u>QEM</u> or <u>aftermarket</u> equivalent part. [<u>Example</u>]



Reference numbers in this diagram can be found in a light blue row below — scroll down to order. Each product listed is an $\underline{\mathsf{OEM}}$ or $\underline{\mathsf{aftermarket}}$ equivalent part. [$\underline{\mathsf{Example}}$]

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
#-	1630-4921A 3	GEAR HOUSING ASSEMBLY, COMPL SEE NOTE 1 IN BLOCK COMMENTS 8015315-8028839 BELGIUM 9043:	U.S. 3801458-4	1316Ò9 AUS	STRALIA	• ,
No Image Available	1630-4921A 3 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-4921A24 (more info)				Unavailable 🗿
No Image Available	1630-4921A24 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-5908A 6 (more info)				Unavailable 👩

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
No Image Available	1630-5908A 6 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-7360A12 (more info)				Unavailable (
No Image Available	1630-7360A12	GEAR HOUSING ASSY O NLA (more info)				Unavailable (
#-	1630-4921A 2	GEAR HOUSING ASSEMBLY, COMPLI SEE NOTE 1 IN BLOCK COMMENTS U 8015315-8028839 BELGIUM 90431	J.S. 3801458-4	131609 AUS	TRALIA	
No Image Available	1630-4921A 2 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-4921A25 (more info)				Unavailable (
No Image Available	1630-4921A25 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-5908A 7 (more info)				Unavailable (
No Image Available	1630-5908A 7 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-7360A13 (more info)				Unavailable (
No Image Available	1630-7360A13 OEM	1630-7360A13 - Gear Housing Assembly, Mercury 110 , NLA (more info)	MERCURY QUICKSILVER	\$400.00	\$400.00	ADD TO CART 1 in stock.
#-	1630-4921A24	GEAR HOUSING ASSEMBLY, COMPLI SEE NOTE 1 IN BLOCK COMMENTS U BELGM 9079489-9102613 CAN 705 8015315-8019089 BELGM 9043194	J.S. 4131610-4 0208-7065472	314384 AUS U.S. 380145	TR 8028840 58-3929194	-8035569
No Image Available	1630-4921A24 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-5908A 6 (more info)				Unavailable (
No Image Available	1630-5908A 6 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-7360A12 (more info)				Unavailable (
No Image Available	1630-7360A12	GEAR HOUSING ASSY O NLA (more info)				Unavailable (
#-	1630-4921A25	GEAR HOUSING ASSEMBLY, COMPLI SEE NOTE 1 IN BLOCK COMMENTS U BELGM 9079489-9102613 CAN 705 8015315-8019089 BELGM 9043194	J.S. 4131610-4 0208-7065472	314384 AUS U.S. 380145	TR 8028840 58-3929194	-8035569
No Image Available Reportages con	1630-4921A25 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-5908A 7 (more info)				Unavailable (
No Image Available	1630-5908A 7 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-7360A13 (more info)				Unavailable (
No Image Available	1630-7360A13 OEM	1630-7360A13 - Gear Housing Assembly, Mercury 110 , NLA (more info)	MERCURY	\$400.00	\$400.00	ADD TO CART 1 in stock.
#-	1630-5908A 6	GEAR HOUSING ASSEMBLY, COMPLI SEE NOTE 1 IN BLOCK COMMENTS U BELGIUM 9102614 AND UP CANADA	J.S. 4314385 A	ND ÚP AUST		
No Image Available	1630-5908A 6 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-7360A12 (more info)				Unavailable (
No Image Available	1630-7360A12	GEAR HOUSING ASSY O NLA (more info)				Unavailable (
#-	1630-5908A 7	GEAR HOUSING ASSEMBLY, COMPLI SEE NOTE 1 IN BLOCK COMMENTS U 8035570 AND UP BELGIUM 910261	JNITED STATES	6 4314385 A	ND ÜP AUST	
No Image Available	1630-5908A 7 Replaced by	GEAR HOUSING ASSY 0 - Replaced by 1630-7360A13 (more info)				Unavailable (

lef. No.	Pa	rt No.	Description	Manufacturer	List Price	Your Price	Order	
No Image Available	1	630-7360A13 OEM	1630-7360A13 - Gear Housing Assembly, Mercury 110 , NLA (more info)	MERCURY	\$400.00	\$400.00	1 in stock.	RT
‡1	10	630-4921A 1	GEAR HOUSING ASSEMBLY (1 requi UNITED STATES 3801458 THRU 431 9043194 THRU 9102613 CANADA 7	4384 AUSTRAI	LIA 8015315	THRU 8035	569 BELGIU	JM
No Image Available	1	630-4921A 1	GEAR HOUSING ASSY O NLA (more info)				Unavailable	(2
±1	10	530-5908A 5	GEAR HOUSING ASSEMBLY (1 requi UNITED STATES 4314385 AND UP A UP CANADA 7065473 AND UP			P BELGIUM S	9102614 AN	ND
No Image Available	1	.630-5908A 5 Replaced by	GEAR HOUSING ASSY O - Replaced by 1630-7360A11 (more info)				Unavailable	(?
	⊕ 1	630-7360A11 OEM	1630-7360A11 - Gear Housing Assembly, NLA (more info)	MERCURY	\$200.00	\$200.00	4 in stock.	RT
2		16-58138	STUD, GEAR HOUSING RO DRIVE SH	AFT HOUSING	(3 7/16") (1	required p	er assembly	y)
No Image Available		16-58138 OEM	<u>16-58138 - Stud, NLA</u> (more info)	MERCURY	\$10.00	\$10.00	ADD TO CA	RT
ŧ3		16-58136	STUD, WATER PUMP HOUSING TO G	EAR HOUSING	(2 3/4") (2	required per	assembly))
No Image Available		16-58136 OEM	<u>16-58136 - Stud, NLA</u> (more info)	MERCURY	\$3.42	\$3.42	ADD TO CA	art (
# 4		31-22756	BEARING, ROLLER - DRIVE SHAFT (1 required per	assembly)			
	Đ,	31-22756 OEM	<u>31-22756 - Bearing</u> (more info)	MERCURY	\$16.90	\$14.47	ADD TO CA	IRT
# 5		17-20032	PIN, DOWEL - LOCATING (1 require	d per assembly	/)			
No Image Available		17-20032 OEM	17-20032 - Pin -Dowel - Priced Individually (more info)	MERCURY QUICKSILVER	\$2.80	\$2.80	ADD TO CA	urt
# 6		26-33613	SEAL, RUBBER - WATER INTAKE TU	BE (1 required	per assembly	/)		
No Image Available		26-33613 OEM	<u>26-33613 - Seal - Priced Individually</u> (more info)	MERCURY	\$3.40	\$3.40	ADD TO CA	URT
‡ 7		12-36555	WASHER, NYLON - INTAKE TUBE SE	AL (1 required	per assembl	y)		
No Image Available Renetation con		12-36555 Replaced by	WASHER @2 O - Replaced by 23-86215 (more info)				Unavailable	(
No Image Available		23-86215 OEM	23-86215 - Spacer - Priced individually (more info)	MERCURY	\$3.00	\$3.00	ADD TO CA	art
#8		35-33425	SCREEN, WATER INTAKE (1 require	d per assembly	<u>'</u>)			
1111	Đ,	35-33425 OEM	35-33425 - Screen, NLA (more info)	MERCURY	\$10.00	\$10.00	ADD TO CA	IRT
#9		10-28642	SCREW, WATER INTAKE SCREEN TO	GEAR HOUSIN	IG (1 require	d per assem	bly)	
No Image Available		10-28642 OEM	10-28642 - Screw - Priced Individually (more info)	MERCURY	\$0.80	\$0.80	ADD TO CA	art (
‡10		10-28634	SCREW, GREASE FILLER HOLE (1 re	quired per asse	embly)			
-		10-28634	SCREW @5 O - Replaced by 10-79953					

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
O ® 0	10-79953 Replaced by	SCREW @5 O - Replaced by 10-79953A 2 (more info)				Unavailable 👩
♣ ○ •	10-79953A 2 Replaced by	SCREW KIT-DRAIN O - Replaced by 10-79953Q 2 (more info)				Unavailable 👩
♣ ○ •	10-79953Q 2 Replaced by	SCREW KIT @2 O - Replaced by 10-79953Q04 (more info)				Unavailable 👩
0 🖲 0	10-79953Q04 OEM	10-79953Q04 - Screw Kit - Priced Individually (more info)	MERCURY QUICKSILVER	\$5.60	\$5.60	ADD TO CART 10+ in stock.
0 ♥ €	18-2244 Aftermarket	18-2244 - Plug Kit, 10-79953A2 (more info)	Sierra	\$2.91	\$1.95	ADD TO CART 10+ in stock.
0 🖲 0	10-79953K04 OEM	10-79953K04 - Screw - Drain - Priced Individually (more info)	MERCURY QUICK SILVER	\$5.60	\$5.60	7 in stock.
#11	12-20260	WASHER, GREASE FILLER HOLE SCI	REW (1 require	d per assemb	ly)	
0 @	12-20260 Replaced by	WASHER @15 O - Replaced by 12-19183 (more info)				Unavailable @
0	12-19183 Replaced by	WASHER-BLK @15 O - Replaced by 12-19183 2 (more info)				Unavailable @
0	12-19183 2 Replaced by	WASHER-ORAN @15 O - Replaced by 12-19183 3 (more info)				Unavailable (?
O •	12-19183 3 OEM	12-19183 3 - Seal -blue - Priced Individually (more info)	MERCURY QUICK SILVER	\$0.94	\$0.94	ADD TO CART 10+ in stock.
0	18-2945-9 Aftermarket	18-2945-9 - Gasket 12-19183 2-Pack (more info) Replaces OEM #0307552	Sierra	\$2.50	\$1.48	ADD TO CART 10+ in stock.
#12	12-20262	WASHER, GREASE VENT HOLE SCRE	W (1 required	per assembly)	
No Image Available	12-20262 Replaced by	WASHER @25 O - Replaced by -19643 (more info)				Unavailable 👩
0	19643 OEM	19643 - Seal - Priced Individually (more info)	MERCURY QUICKSILVER	\$0.90	\$0.90	ADD TO CART 10+ in stock.
#13	10-28653	SCREW, GREASE VENT HOLE (1 req	uired per asser	nbly)		
⊕ •	10-28653 OEM	10-28653 - Screw - Priced individually (more info)	MERCURY	\$1.80	\$1.80	ADD TO CART 10+ in stock.
#14	63556A 1	SHAFT ASSEMBLY, SHIFT(SHORT S UNITED STATES 3801458 THRU 41: 9043194 THRU 9079488 CANADA 7	31609 AUSTRA	LIA 8015315		839 BELGIUM
No Image Available	63556A 1	63556A 1 - Shaft Assembly (more info)	MERCURY QUICK SILVER	\$35.00	\$35.00	ADD TO CART 1 in stock.
No Image Available	71659A 1 OEM	71659A 1 - Shaft Assembly, NLA (more info)	MERCURY QUICKSILVER	\$40.00	\$40.00	4 in stock.
#14	63557A 1	SHAFT ASSEMBLY, SHIFT (LONG SHUNITED STATES 3801458 THRU 4139043194 THRU 9079488 CANADA 7	31609 AUSTRA	LIA 8015315		839 BELGIUM
No Image Available	63557A 1 Replaced by	SHAFT ASSY O - Replaced by -71658A				Unavailable 👩
	*	(more info)				

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
0	71658A 1 OEM	71658A 1 - Shaft Assembly, NLA (more info)	MERCURY	\$50.00	\$50.00	9 in stock.
#14	71659A 1	SHAFT ASSEMBLY, SHIFT(SHORT SI UNITED STATES 4131610 AND UP A UP CANADA 7050208 AND UP	, , .	•	• /	9079489 AND
No Image Available	71659A 1 OEM	71659A 1 - Shaft Assembly, NLA (more info)	MERCURY	\$40.00	\$40.00	4 in stock.
#14	71658A 1	SHAFT ASSEMBLY, SHIFT(LONG SHAUNITED STATES 4131610 AND UP AUP CANADA 7050208 AND UP				9079489 AND
€ (71658A 1 OEM	71658A 1 - Shaft Assembly, NLA (more info)	MERCURY QUICKSILVER	\$50.00	\$50.00	9 in stock.
#15	53-22899	RING, RETAINING - SHIFT SHAFT (1 required per	assembly)		
No Image Available Renelaçõeses	53-22899 ОЕМ	53-22899 - E Ring - Priced individually (more info)	MERCURY QUICK SILVER	\$1.60	\$1.60	Available to order: Usually ships within 8 days
#16	23-30676A 1	BUSHING ASSEMBLY, SHIFT SHAFT	(1 required pe	r assembly)		
9 •	23-30676A 1 OEM	23-30676A 1 - Bushing (more info)	PERCURY	\$81.80	\$70.05	9 in stock.
#17	25-26802	"O" RING, SHIFT SHAFT BUSHING (1 required per	assembly)		
O ®	25-26802 OEM	25-26802 - O-ring - Priced Individually (more info)	MERCURY QUICKSILVER	\$2.70	\$2.70	Available to order: Usually ships within 8 days
O •	18-7180-9 Aftermarket	18-7180-9 - O-ring (PK5) 925055 (more info) Replaces OEM #0303347	Sierra	\$13.11	\$10.10	1 in stock.
#18	26-30696	OIL SEAL, SHIFT SHAFT BUSHING (1 required per	assembly)		
O •	26-30696 OEM	26-30696 - Seal - Priced Individually (more info)	MERCURY	\$5.60	\$5.60	10+ in stock.
O •	18-8308 Aftermarket	18-8308 - Seal, 26-30696 (more info)	Sierra	\$5.26	\$4.06	2 in stock.
#19	10-39149	SCREW, SHIFT SHAFT BUSHING RE	TAINER (1/2")	(1 required p	er assembl	y)
No Image Available	10-39149 OEM	10-39149 - Screw, NLA (more info)	MERCURY QUICKSILVER	\$6.25	\$6.25	10+ in stock.
#20	43-48579	GEAR, PINION (1 required per asse	mbly)			
No Image Available menotoppasen	43-48579 OEM	43-48579 - Pinion Gear (more info)	MERCURY	\$22.90	\$22.90	5 in stock.
€ (43-98696 OEM	<u>43-98696 - Pinion Gear</u> (more info)	PERCURY	\$105.83	\$105.83	6 in stock.
#21	14-30377	TAB WASHER, PINION GEAR TO DR	IVE SHAFT SCR	REW (1 requir	ed per asse	mbly)
No Image Available	14-30377 OEM	14-30377 - Tab Washer - Priced individually (more info)	MERCURY	\$8.25	\$8.25	ADD TO CART 10+ in stock.
#22	10-30376	SCREW, PINION GEAR TO DRIVE SH	IAFT (3/4") (1	required per	assembly)	
No Image Available Rentespasses	10-30376 OEM	10-30376 - Screw, NLA (more info)	MERCURY	\$1.25	\$1.25	ADD TO CART 10+ in stock.

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order	
#23	45-64257	DRIVE SHAFT(SHORT SHAFT) (1 re UNITED STATES 3801458 THRU 41 9043194 THRU 9079488 CANADA 7	31609 AUSTRA	LIA 8015315	THRU 8028	839 BELGI	UM
No Image Available	45-64257 Replaced by	DRIVE SHAFT O - Replaced by 45-75034A 1 (more info)				Unavailable	e (
No Image Available	45-75034A 1	DRIVE SHAFT ASSY O NLA (more info)				Unavailable	÷ (
#23	45-64258	DRIVE SHAFT(LONG SHAFT) (1 req UNITED STATES 3801458 THRU 41 9043194 THRU 9079488 CANADA 7	31609 AUSTRA	LIA 8015315	THRU 8028	839 BELGI	UM
No Image Available	45-64258 Replaced by	DRIVE SHAFT O - Replaced by 45-75033A 1 (more info)				Unavailable	9 (
No Image Available	45-75033A 1	45-75033A 1 - Drive Shaft Assembly, NLA (more info)	MERCURY	\$500.00	\$500.00	2 in stock.	ART
#23	45-74851	DRIVE SHAFT(SHORT SHAFT) (1 re UNITED STATES 4131610 AND UP UP CANADA 7050208 AND UP			P BELGIUM	9079489 A	ND
No Image Available	45-74851 Replaced by	DRIVE SHAFT O - Replaced by 45-75034 (more info)				Unavailable	a (
No Image Available	45-75034	DRIVE SHAFT O NLA (more info)				Unavailable	e (
#23	45-74850	DRIVE SHAFT(LONG SHAFT) (1 req UNITED STATES 4131610 AND UP UP CANADA 7050208 AND UP			P BELGIUM	9079489 A	ND
No Image Available	45-74850 OEM	45-74850 - Drive Shaft (more info)	MERCURY QUICKSILVER	\$149.95	\$149.95	ADD TO CA	ART
No Image Available	45-75033 OEM	45-75033 - Drive Shaft, NLA (more info)	MERCURY QUICK SILVER	\$250.00	\$250.00	ADD TO CA	ART
#24	15-30527A 1	SHIM ASSEMBLY, BALL BEARING To assembly)	O GEAR HOUSII	NG (.002-3-5	-10) (AR re	quired per	
No Image Available	15-30527A 1 OEM	<u>15-30527A 1 - Shim Set, NLA</u> (more info)	MERCURY QUICKSILVER	\$12.50	\$12.50	ADD TO CA	ART
#25	30-33076	BEARING, BALL - DRIVE SHAFT (1 UNITED STATES 3801458 THRU 41 9043194 THRU 9079488 CANADA 7	31609 AUSTRA	LIA 8015315	THRU 8028	839 BELGI	UM
◎ ⊕	30-33076 OEM	30-33076 - Ball Bearing (more info)	MERCURY QUICKSILVER	\$48.90	\$41.87	1 in stock.	ART
#25	30-70944	BEARING, BALL - DRIVE SHAFT (1 UNITED STATES 4131610 AND UP UP CANADA 7050208 AND UP			P BELGIUM	9079489 A	ND
90=70944#	30-70944 OEM	30-70944 - Ball Bearing (more info)	MERCURY	\$48.30	\$41.36	1 in stock.	ART
#26	53-30523	RING, RETAINING - BALL BEARING	TO DRIVE SHA	NFT (1 require	ed per asser	nbly)	
No Image Available	53-30523 OEM	53-30523 - Retaining Ring (more info)	MERCURY	\$0.85	\$0.85	Available to order: Usually ships within 8 days	ART
#28	46-46893A 3	WATER PUMP HOUSING ASSEMBLY UNITED STATES 3801458 THRU 41 9043194 THRU 9079488 CANADA 7	31609 AUSTRA	LIA 8015315	THRU 8028	·	UM

Ref. No.		Part No.	Description	Manufacturer	List Price	Your Price	Order	
	⊕ ,	46-46893A 3 OEM	46-46893A 3 - Housing Assembly (more info)	MERCURY QUICKSILVER	\$68.60	\$58.75	2 in stock.	RT 3
#28		46-70941A 1	WATER PUMP HOUSING ASSEMBLY UNITED STATES 4131610 AND UP UP CANADA 7050208 AND UP			P BELGIUM S	9079489 AN	ND
	⊕,	46-70941A 1 Replaced by	HOUSING ASSY O - Replaced by 46-70941T01 (more info)				Unavailable	(2)
0	⊕,	46-70941T01 OEM	46-70941T01 - Housing Assembly (more info)	MERCURY	\$41.17	\$41.17	ADD TO CA 2 in stock.	RT 2
#29		25-29439	"O" RING, WATER PUMP HOUSING	(1 required per	r assembly)			
\bigcirc	⊕,	25-29439 OEM	25-29439 - O-ring - Priced Individually (more info)	PERCURY QUICK SILVER	\$2.00	\$2.00	Available to order: Usually ships within 8 days	RT ②
	⊕_	18-7156-9 Aftermarket	18-7156-9 - (PK5) O-ring 25-29439 (more info) Replaces OEM #0309731	Sierra	\$11.89	\$7.30	2 in stock.	RT ②
#30		26-30900	OIL SEAL, WATER PUMP HOUSING	(1 required per	assembly)			
0	⊕,	26-30900 Replaced by	SEAL @2 O - Replaced by 26-30900T (more info)				Unavailable	?
0	⊕ (26-30900T OEM	26-30900T - Seal - Priced Individually (more info)	PERCURY QUICK SILVER	\$11.90	\$11.90	Available to order: Usually ships within 8 days	RT ?
0	⊕ ,	18-8310 Aftermarket	<u>18-8310 - Seal, 26-30900</u> (more info)	Sierra	\$11.33	\$8.62	4 in stock.	RT 2
#32		32-34293	TUBE, WATER INTAKE (1 required	per assembly)				
St-3v295	⊕ ູ	32-34293 OEM	32-34293 - Tubing, NLA (more info)	MERCURY	\$18.75	\$18.75	ADD TO CA	RT ②
#33		70977	INSERT, WATER PUMP HOUSING (1 required per a	issembly)			
O	⊕ ູ	70977 Replaced by	INSERT O - Replaced by -70977T (more info)				Unavailable	?
0	⊕ ູ	70977T OEM	70977T - Insert (more info)	MERCURY	\$8.40	\$8.40	ADD TO CA	RT ?
9	⊕ ູ	18-3113 Aftermarket	<u>18-3113 - Cup 70977</u> (more info)	Sierra	\$9.18	\$5.68	1 in stock.	RT ②
#34		28-56655	KEY, IMPELLER DRIVE (1 required	per assembly)				
No Image Available		28-56655 Replaced by	KEY @5 O - Replaced by 28-8M0032835 (more info)				Unavailable	(2)
	⊕,	28-8M0032835 OEM	28-8M0032835 - Key (more info)	MERCURY	\$4.10	\$4.10	ADD TO CA	RT ②
#35		47-65957	IMPELLER, WATER PUMP (1 requir	ed per assembly	y)			
No Image Available		47-65957 Replaced by	IMPELLER @4 O - Replaced by 47-89981 (more info)				Unavailable	?
*	⊕ ,	47-89981 OEM	<u>47-89981 - Impeller</u> (more info)	MERCURY	\$15.92	\$15.92	ADD TO CA	RT ②

Ref. No.		Part No.	Description	Manufacturer	List Price	Your Price	Order
女	⊕,	18-3039 Aftermarket	18-3039 - Impeller 47-89981 (more info)	Sierra	\$13.53	\$8.96	ADD TO CART 10+ in stock.
#36		46895	PLATE, FACE - WATER PUMP HOUS assembly)	ING TO WATER	PUMP COVER	t (1 required	l per
0	⊕,	46895 OEM	46895 - Faceplate - Priced Individually (more info)	MERCURY	\$3.40	\$3.40	4 in stock.
0	⊕(18-3139 Aftermarket	18-3139 - Plate, 46895 (more info)	Sierra	\$2.69	\$2.48	4 in stock.
#37		46896A 1	WATER PUMP COVER ASSEMBLY (1	. required per a	ssembly)		
No Image Available		46896A 1 Replaced by	COVER ASSY O - Replaced by -93224A 1 (more info)				Unavailable 👩
٠	⊕(93224A 1 OEM	93224A 1 - Cover Assembly (more info)	MERCURY	\$24.00	\$20.55	ADD TO CART 8 in stock.
#38		26-36558	SEAL, WATER PUMP COVER (1 requ	iired per assem	bly)		
8	⊕ (26-36558 OEM	26-36558 - Seal - Priced Individually (more info)	MERCURY QUICKSILVER	\$3.80	\$3.80	ADD TO CART 10+ in stock.
#39		12-36554	WASHER, NYLON- WATER PUMP CO	OVER (1 require	d per assemb	oly)	
No Image Available		12-36554 Replaced by	WASHER @3 O - Replaced by 23-86214 (more info)				Unavailable 🗿
No Image Available		23-86214 Replaced by	SPACER @3 O - Replaced by 23-13127 (more info)				Unavailable 🗿
0	⊕_(23-13127 OEM	23-13127 - Spacer - Priced individually (more info)	MERCURY QUICKSILVER	\$3.60	\$3.60	ADD TO CART 10+ in stock.
#40		26-30913	OIL SEAL, WATER PUMP COVER (1	required per as	sembly)		
0	⊕,	26-30913 OEM	26-30913 - Seal - Priced Individually (more info)	PERCURY	\$16.30	\$13.96	Available to order: Usually ships within 8 days
0	⊕(18-0516 Aftermarket	18-0516 - Seal, 26-30913 (more info)	Sierra	\$9.14	\$7.19	1 in stock.
#41		12-20533	WASHER, WATER PUMP HOUSING	AND COVER STU	JDS (2 requir	ed per asse	mbly)
No Image Available		12-20533 OEM	12-20533 - Washer - Priced Individually (more info)	WERCURY QUICKSILVER	\$1.10	\$1.10	ADD TO CART 10+ in stock.
#42		11-35888	NUT, WATER PUMP HOUSING AND	COVER STUDS	(2 required p	er assembly)
	⊕,	11-35888 OEM	11-35888 - Nut - Priced Individually (more info)	MERCURY QUICKSILVER	\$4.60	\$4.60	Available to order: Usually ships within 8 days
	⊕,	18-3722-9 Aftermarket	18-3722-9 - Lucknut, 121731, 11-35888 (more info) Replaces OEM #0121731	Sierra	\$13.28	\$7.33	Available to order: Usually ships within 8 days
#43		25-30526	RING, RUBBER - CENTRIFUGAL SLI	NGER (DRIVE S	SHAFT) (1 req	uired per a	•
0	⊕_	25-30526 OEM	25-30526 - O-ring - Priced Individually (more info)	MERCURY	\$1.80	\$1.80	ADD TO CART 10+ in stock.
#44		23-31792	SLEEVE, GUIDE - WATER INLET TU	BE (1 required	per assembly)	



Note the second second

Subscribe to the MarineEngine.com Newsletter

Periodically we'll send you Tech Tips, How-To's and Boating Information. Just enter your e-mail address and click Subscribe!

email address Subscribe

You can easily unsubscribe from the newsletter at any time.

Why Us & Reviews

« Previous | Next »

Boat Repair Forum

□ Video Gallery

HOME | CONTACT | SHIPPING | RETURNS | CART

Boat Engine PartsBoat Motor ManualsBoat Accessories

About Us | Terms of Use | Privacy Policy

© 2015 MarineEngine.com, Inc. All rights reserved.

X

MarineEngine.com, 184 Jones Drive, Brandon, VT 05733 USA

Phone: 802-247-4700 | Fax: 802-419-3055 | eMail: <u>info@marineengine.com</u>