


Parts for Mercury Marine 7.5 HP CYLINDER BLOCK AND CRANKCASE ASSEMBLY

Revise Search: Start Over > Different Engine Model > Different Serial Number Range > Different Component

YOU ARE HERE: MERCURY > 7.5 HP > 3801458 THRU 4851692 (USA) > CYLINDER BLOCK AND CRANKCASE ASSEMBLY

« Previous | Next »

Reference numbers in this diagram can be found in a light blue row below — scroll down to order. Each product listed is an <u>QEM</u> or <u>aftermarket</u> equivalent part. [<u>Example</u>]



Reference numbers in this diagram can be found in a light blue row below — scroll down to order. Each product listed is an <u>OEM</u> or <u>aftermarket</u> equivalent part. [<u>Example</u>]

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
#1	837-5284A 4	CYLINDER BLOCK AND CRANKCA UNITED STATES 3801458 THRU 9043194 THRU 9079488 CANAD	4131609 AUSTRA	LIA 8015315	• /	9 BELGIUM
No Image Available	837-5284A 4 Replaced by	CYLINDER BLOCK O - Replaced by 837-5956A 3 (more info)				Unavailable 🗿
No Image Available	837-5956A 3 Replaced by	CYLINDER BLOCK O - Replaced by 837-6111A 4 (more info)				Unavailable 👩

	Part No.	Description	Manufacturer	List Price	Your Price	Order
No Image Available	837-6111A 4 Replaced by	CYLINDER BLOCK O - Replaced by 837-6298A 4 (more info)				Unavailable 🔞
No Image Available	837-6298A 4 Replaced by	CYLINDER BLK ASSY O - Replaced by 837-6543A 5 (more info)				Unavailable 👩
No Image Available	837-6543A 5	CYLINDER BLOCK O NLA (more info)				Unavailable 👩
#1	837-5675A 3	CYLINDER BLOCK AND CRANKCASE UNITED STATES 4131610 THRU 424 9079489 THRU 9092863 CANADA 7	18574 AUSTRAI	LIA 8028840	• /	14 BELGIUM
No Image Available	837-5675A 3 Replaced by	CYLINDER BLOCK O - Replaced by 837-5955A 3 (more info)				Unavailable 👩
No Image Available	837-5955A 3 Replaced by	CYLINDER BLOCK O - Replaced by 837-6112A 4 (more info)				Unavailable 👩
No Image Available	837-6112A 4 Replaced by	CYLINDER BLOCK O - Replaced by 837-6414A 4 (more info)				Unavailable 👩
No Image Available	837-6414A 4 Replaced by	CYLINDER BLK ASSY O - Replaced by 837-6542A 5 (more info)				Unavailable 🔞
No Image Available	837-6542A 5	CYLINDER BLOCK O NLA (more info)				Unavailable 👩
#1	837-5991A 3	CYLINDER BLOCK AND CRANKCASE UNITED STATES 4248575 THRU 43: 9092864 THRU 9102613 CANADA 7	L4384 AUSTRAI	LIA 8031715	• •	69 BELGIUM
No Image Available	837-5991A 3 Replaced by	CYLINDER BLOCK O - Replaced by 837-5955A 3 (more info)				Unavailable 👩
	*	(more inio)				onavanasio (
No Image Available	837-5955A 3 Replaced by	CYLINDER BLOCK O - Replaced by 837-6112A 4 (more info)				
	837-5955A 3 Replaced by	CYLINDER BLOCK O - Replaced by 837-6112A 4				Unavailable (?
Available Resultageaum No Image Available	837-5955A 3 Replaced by # 837-6112A 4 Replaced by	CYLINDER BLOCK O - Replaced by 837-6112A 4 (more info) CYLINDER BLOCK O - Replaced by 837-6414A 4				Unavailable (?
Available **Rentriguesia** No Image Available **Rentriguesia** No Image	837-5955A 3 Replaced by 837-6112A 4 Replaced by 837-6414A 4 Replaced by	CYLINDER BLOCK O - Replaced by 837-6112A 4 (more info) CYLINDER BLOCK O - Replaced by 837-6414A 4 (more info) CYLINDER BLK ASSY O - Replaced by 837-6542A 5				Unavailable (? Unavailable (? Unavailable (?
Available Receives as No Image Available Receives as No Image Available Receives as No Image Available Receives as	837-5955A 3 Replaced by 837-6112A 4 Replaced by 837-6414A 4 Replaced by 837-6542A 5	CYLINDER BLOCK O - Replaced by 837-6112A 4 (more info) CYLINDER BLOCK O - Replaced by 837-6414A 4 (more info) CYLINDER BLK ASSY O - Replaced by 837-6542A 5 (more info) CYLINDER BLOCK O NLA	97536 AUSTRAI	LIA 8035570	• /	Unavailable (? Unavailable (? Unavailable (?
Available menticus sa No Image Available menticus sa	837-5955A 3 Replaced by 837-6112A 4 Replaced by 837-6414A 4 Replaced by 837-6542A 5	CYLINDER BLOCK O - Replaced by 837-6112A 4 (more info) CYLINDER BLOCK O - Replaced by 837-6414A 4 (more info) CYLINDER BLK ASSY O - Replaced by 837-6542A 5 (more info) CYLINDER BLOCK O NLA (more info) CYLINDER BLOCK AND CRANKCASE UNITED STATES 4314385 THRU 438	97536 AUSTRAI	LIA 8035570	• /	Unavailable (? Unavailable (? Unavailable (? Unavailable (? 49 BELGIUM
Available Modrage Available	837-5955A 3 Replaced by 837-6112A 4 Replaced by 837-6414A 4 Replaced by 837-6542A 5 837-5955A 3 837-5955A 3 Replaced by	CYLINDER BLOCK O - Replaced by 837-6112A 4 (more info) CYLINDER BLOCK O - Replaced by 837-6414A 4 (more info) CYLINDER BLK ASSY O - Replaced by 837-6542A 5 (more info) CYLINDER BLOCK O NLA (more info) CYLINDER BLOCK AND CRANKCASE UNITED STATES 4314385 THRU 43: 9102614 THRU 9115164 CANADA 7 CYLINDER BLOCK O - Replaced by 837-6112A 4	97536 AUSTRAI	LIA 8035570	• /	Unavailable (? Unavailable (? Unavailable (? 49 BELGIUM Unavailable (?
No Image Available Receives as No Image Available Receives Avai	837-5955A 3 Replaced by 837-6112A 4 Replaced by 837-6414A 4 Replaced by 837-6542A 5 837-5955A 3 837-5955A 3 837-5955A 4 Replaced by 837-6112A 4 Replaced by	CYLINDER BLOCK O - Replaced by 837-6112A 4 (more info) CYLINDER BLOCK O - Replaced by 837-6414A 4 (more info) CYLINDER BLK ASSY O - Replaced by 837-6542A 5 (more info) CYLINDER BLOCK O NLA (more info) CYLINDER BLOCK AND CRANKCASE UNITED STATES 4314385 THRU 439 9102614 THRU 9115164 CANADA 7 CYLINDER BLOCK O - Replaced by 837-6112A 4 (more info) CYLINDER BLOCK O - Replaced by 837-6414A 4	97536 AUSTRAI	LIA 8035570	• /	Unavailable (?) Unavailable (?) Unavailable (?)

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order	
#1	837-6112A 4	CYLINDER BLOCK AND CRANKCAS UNITED STATES 4397537 THRU 46 9115165 THRU 9150904 CANADA	91221 AUSTRAL	.IA 8038450		74 BELGIUN	4
No Image Available	837-6112A 4 Replaced by	CYLINDER BLOCK O - Replaced by 837-6414A 4 (more info)				Unavailable	(?
No Image Available	837-6414A 4 Replaced by	CYLINDER BLK ASSY O - Replaced by 837-6542A 5 (more info)				Unavailable	(?
No Image Available	837-6542A 5	CYLINDER BLOCK O NLA (more info)				Unavailable	(?
#1	837-6414A 4	CYLINDER BLOCK AND CRANKCAS UNITED STATES 4691222 AND UP UP CANADA 7095423 AND UP				L50905 ANI	D
No Image Available	837-6414A 4 Replaced by	CYLINDER BLK ASSY O - Replaced by 837-6542A 5 (more info)				Unavailable	(?
No Image Available	837-6542A 5	CYLINDER BLOCK O NLA (more info)				Unavailable	(?
#2	16-72809	STUD, BLOCK AND CRANKCASE TO	DRIVE SHAFT H	OUSING (6 re	equired per a	ssembly)	
No Image Available	16-72809 Replaced by	STUD O - Replaced by 16-72809 1 (more info)				Unavailable	2
No Image Available	16-72809 1 OEM	16-72809 1 - Stud (more info)	MERCURY QUICKSILVER	\$6.40	\$6.40	Available to order: Usually ships within 8 days	RT
#3	16-66357	STUD, CARBURETOR MOUNTING (2	required per as	sembly)			
No Image Available	16-66357 Replaced by	STUD O - Replaced by 10-65746 1 (more info)				Unavailable	(?
90	⊕ 10-65746 1 OEM	10-65746 1 - Screw (more info)	MERCURY QUICKSILVER	\$1.20	\$1.20	Available to order: Usually ships within 8 days	ART 2
#4	17-46912	PIN, DOWEL - CRANKCASE TO CYL	INDER BLOCK (2	required per	assembly)		
No Image Available	17-46912 OEM	17-46912 - Pin -Dowel (more info)	MERCURY QUICKSILVER	\$0.50	\$0.50	ADD TO CA	IRT
No Image Available	17-85500 OEM	<u>17-85500 - Pin -Dowel</u> (more info)	MERCURY	\$3.90	\$3.90	ADD TO CA	ART
#5	10-23015	SCREW, ADJ THROTTLE CONTRO UNITED STATES 3801458 THRU 43 9043194 THRU 9115164 CANADA	97536 AUSTRAL	.IA 8015315	• /	49 BELGIUN	4
	⊕ 10-23015 OEM	<u>10-23015 - Screw</u> (more info)	MERCURY	\$1.40	\$1.40	ADD TO CA	IRT
#5	10-54467	SCREW, ADJ THROTTLE CONTRO UNITED STATES 4397537 AND UP UP CANADA 7076123 AND UP				L15165 ANI	D
No Image Available	10-54467 ОЕМ	<u>10-54467 - Screw</u> (more info)	MERCURY	\$0.94	\$0.94	ADD TO CA	IRT
S.	① 10-69560 OEM	10-69560 - Screw (more info)	MERCURY QUICKSILVER	\$2.12	\$2.12	3 in stock.	ART
		NUT, THROTTLE CONTROL ADJUST					

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order	
No Image Available	11-68219 OEM	11-68219 - Nut - Priced Individually (more info)	MERCURY	\$1.90	\$1.90	ADD TO CAR 10+ in stock.	RT
#7	21-64871A 1	VALVE ASSEMBLY, BLEED DRAIN (1	required per a	ssembly)			
No Image Available	21-64871A 1 OEM	21-64871A 1 - Check Valve Kit, NLA (more info)	PERCURY	\$18.00	\$18.00	ADD TO CAR	RT (
#8	32-60584	HOSE, BLEED DRAIN (6 1/2') (1 red	quired per asse	embly)			
No Image Available	32-60584 Replaced by	HOSE O - Replaced by 32-60580 78 (more info)				Unavailable	(
No Image Available	32-60580 78 Replaced by	FUEL LINE O - Replaced by 32-99130 78 (more info)				Unavailable	(
No Image Available Renotagos con	32-99130 78 Replaced by	TUBING-26 INCH O - Replaced by 32-99130122 (more info)				Unavailable	(
O •	32-99130122 Replaced by	TUBING-20 FEET O - Replaced by 32-892024122 (more info)				Unavailable	(
Q 0	32-892024122 OEM	32-892024122 - Tubing - 20 Feet (more info)	MERCURY QUICKSILVER	\$39.70	\$33.99	Available to order: Usually ships within 8 days	RT
#9	54-56223	CLAMP, BLEED HOSE ATTACHING (2	2 required per a	assembly)			
No Image Available	54-56223	CLAMP @2 O NLA (more info)				Unavailable	(
#10	22-61294	ELBOW, BLEED(MANUAL) (1 require	ed per assembl	y)			
No Image Available	22-61294 OEM	22-61294 - Elbow, NLA (more info)	PERCURY	\$40.00	\$40.00	ADD TO CAR	RT
#10	22-56759	ELBOW, BLEED(ELECTRIC) (1 requi	red per asseml	oly)			
No Image Available	22-56759 OEM	22-56759 - Fitting (more info)	MERCURY	\$7.80	\$7.80	ADD TO CAR	er (
#11	22-25885	ELBOW, TELL TALE - CYLINDER BLO	OCK (1 required	l per assembly	')		
No Image Available	22-25885 Replaced by	ELBOW @3 O - Replaced by 22-99664 (more info)				Unavailable	(
No Image Available	22-99664 Replaced by	ELBOW O - Replaced by 22-99664 1 (more info)				Unavailable	(
No Image Available	22-99664 1 Replaced by	ELBOW O - Replaced by 22-99664 2 (more info)				Unavailable	(
⊕	22-99664 2 OEM	22-99664 2 - Elbow (more info)	MERCURY	\$1.80	\$1.80	ADD TO CAR 8 in stock.	RT
#12	10-31294	SCREW, CRANKCASE TO CYLINDER UNITED STATES 3801458 THRU 469 9043194 THRU 9150904 CANADA 7	91221 AUSTRA	LIA 8015315 T		74 BELGIUM	i
No Image Available	10-31294 Replaced by	SCREW @5 O - Replaced by 10-64278 (more info)				Unavailable	(
0	10-64278 OEM	10-64278 - Screw, NLA (more info)	MERCURY	\$1.50	\$1.50	ADD TO CAR	RT

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
#13	10-24264	SCREW, CRANKCASE TO CYLINDER UNITED STATES 3801458 THRU 40 9043194 THRU 9150904 CANADA	591221 AUSTRAL	IÀ 8015315 T		
No Image Available	91-24264	INSERT O NLA (more info)				Unavailable 🗿
#14	11-24652	NUT, CRANKCASE FASTENING SCR UNITED STATES 3801458 THRU 40 9043194 THRU 9150904 CANADA	591221 AUSTRAL	IA 8015315 T		4 BELGIUM
8	11-24652 OEM	11-24652 - Nut - Priced individually (more info)	MERCURY QUICKSILVER	\$1.20	\$1.20	ADD TO CART 10+ in stock.
#12	10-76621	SCREW, CRANKCASE TO CYLINDER UNITED STATES 4691222 AND UP UP CANADA 7095423 AND UP				50905 AND
No Image Available	10-76621 OEM	10-76621 - Screw, NLA (more info)	MERCURY QUICKSILVER	\$1.25	\$1.25	4 in stock.
#13	10-73280	SCREW, CRANKCASE TO CYLINDER UNITED STATES 4691222 AND UP UP CANADA 7095423 AND UP				
No Image Available	10-73280	SCREW @5 O NLA (more info)				Unavailable 🗿
#15	10-26801	SCREW, MAIN BEARING LOCKING UNITED STATES 4691222 AND UP UP CANADA 7095423 AND UP				50905 AND
No Image Available	10-26801 OEM	10-26801 - Screw - Priced individually (more info)	MERCURY	\$0.35	\$0.35	ADD TO CART 10+ in stock.
	10-98260 OEM	<u>10-98260 - Screw</u> (more info)	MERCURY QUICKSILVER	\$0.80	\$0.80	2 in stock.
#16	14-20091	TAB WASHER, MAIN BEARING LOC	KING SCREW (1	required per	assembly)	
No Image Available	14-20091 OEM	14-20091 - Tab Washer - Priced individually (more info)	PERCURY	\$1.40	\$1.40	Available to order: Usually ships within 8 days
#17	15-31412A 1	SHIM, UPPER HOUSING TO CYLIN	DER BLOCK (.002	-3-5-10) (AR	required per	assembly)
No Image Available	15-31412A 1 OEM	<u>15-31412A 1 - Shim Set, NLA</u> (more info)	PERCURY QUICKSILVER	\$9.00	\$9.00	ADD TO CART 10+ in stock.
#18	1157-5279A 1	BEARING HOUSING ASSEMBLY, UNITED STATES 3801458 THRU 439043194 THRU 9115164 CANADA	397536 AUSTRAL	ÍA 8015315 Í		9 BELGIUM
No Image Available	1157-5279A Replaced by 1	END CAP ASSY O - Replaced by 1164-6110A 1 (more info)				Unavailable 🗿
No Image Available	1164-6110A Replaced by 1	END CAP ASSY O - Replaced by 1164-6413A 1 (more info)				Unavailable 👩
No Image Available	1164-6413A 1 OEM	1164-6413A 1 - End Cap, NLA (more info)	MERCURY QUICK SILVER	\$115.00	\$115.00	ADD TO CART 6 in stock.
#18	1164-6110A 1	BEARING HOUSING ASSEMBLY, UI UNITED STATES 4397537 THRU 40 9115165 THRU 9150904 CANADA	591221 AUSTRAL	IA 8038450 T		4 BELGIUM
No Image Available	1164-6110A Replaced by 1	END CAP ASSY O - Replaced by 1164-6413A 1 (more info)				Unavailable 🗿

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
No Image Available	1164-6413A 1 OEM	<u>1164-6413A 1 - End Cap, NLA</u> (more info)	MERCURY	\$115.00	\$115.00	ADD TO CART
#18	1164-6413A 1	BEARING HOUSING ASSEMBLY, UP UNITED STATES 4691222 AND UP UP CANADA 7095423 AND UP				.50905 AND
No Image Available	1164-6413A 1 OEM	1164-6413A 1 - End Cap, NLA (more info)	MERCURY	\$115.00	\$115.00	ADD TO CART
#19	30-20861	BEARING, BALL - UPPER BEARING	HOUSING (1 re	quired per ass	embly)	
No Image Available Arguetagos con	30-20861 Replaced by	BALL BEARING@2 O - Replaced by 30-72961 (more info)				Unavailable
O •	30-72961 OEM	30-72961 - Ball Bearing (more info)	PERCURY	\$18.70	\$16.02	Available to order: Usually ships within 8 days
O •	18-1398 Aftermarket	<u>18-1398 - Bearing, 30-72961</u> (more info)	Sierra	\$15.69	\$14.48	ADD TO CART
#20	31-31410	BEARING, ROLLER - UPPER BEARIN	NG HOUSING (1	required per a	assembly)	
●	31-31410 OEM	31-31410 - Bearing, NLA (more info)	MERCURY QUICKSILVER	\$16.00	\$16.00	ADD TO CART
#21	26-66301	OIL SEAL, UPPER BEARING HOUSI	NG (1 required	per assembly)		
0	26-66301 OEM	26-66301 - Seal - Priced Individually (more info)	MERCURY	\$16.10	\$13.78	ADD TO CART
#22	25-20863	"O" RING, UPPER BEARING HOUSI	NG (1 required	per assembly)		
\bigcirc	25-20863 OEM	25-20863 - O-ring - Priced Individually (more info)	MERCURY	\$2.30	\$2.30	ADD TO CART
9 88 0	18-7152-9 Aftermarket	18-7152-9 - O-ring 25-20863 (more info) Replaces OEM #0307082	Sierra	\$13.59	\$8.29	ADD TO CART
#23	10-39002	SCREW, UPPER BEARING HOUSING UNITED STATES 3801458 THRU 46 9043194 THRU 9150904 CANADA	91221 AUSTRA	LIA 8015315 T		74 BELGIUM
No Image Available	10-39002 OEM	10-39002 - Screw, NLA (more info)	MERCURY	\$1.25	\$1.25	7 in stock.
#23	10-76611	SCREW, UPPER BEARING HOUSING UNITED STATES 4691222 AND UP UP CANADA 7095423 AND UP		•	• /	.50905 AND
No Image Available	10-76611 OEM	10-76611 - Screw, NLA (more info)	MERCURY QUICK SILVER	\$1.25	\$1.25	ADD TO CART
#23A	14-76610	TAB WASHER, UPPER BEARING HO UNITED STATES 4691222 AND UP UP CANADA 7095423 AND UP				.50905 AND
No Image Available ####################################	14-76610 Replaced by	TAB WASHER @5 O - Replaced by 14-78102 (more info)				Unavailable
No Image Available	14-78102 OEM	14-78102 - Tab Washer, NLA (more info)	MERCURY	\$1.35	\$1.35	ADD TO CART
#24	27-31434	GASKET, TRANSFER PORT COVER (1 required per a	assembly)		
No Image	27-31434	GASKET @3 O - Replaced by				

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
No Image Available Memotropiscon	27-78032 OEM	27-78032 - Gasket - Priced individually (more info)	MERCURY QUICK SILVER	\$2.00	\$2.00	ADD TO CART 10+ in stock.
No Image Available sentropuses	27-78032 1 OEM	<u>27-78032</u> <u>1 - Gasket</u> (more info)	MERCURY QUICK SILVER	\$4.50	\$4.50	Available to order: Usually ships within 8 days
#25	61155	COVER, TRANSFER PORT - MANUAL	. (1 required pe	r assembly)		
No Image Available	61155	COVER O NLA (more info)				Unavailable 👩
#26	10-26537	SCREW, PORT COVER TO CYLINDER	R BLOCK (1/2")	- MANUAL (3	required per	assembly)
No Image Available	10-26537 OEM	10-26537 - Screw, NLA (more info)	PERCURY QUICKSILVER	\$1.25	\$1.25	ADD TO CART 10+ in stock.
#25	74344	COVER, TRANSFER PORT - ELECTRI	C (1 required p	er assembly)		
No Image Available	74344	COVER O NLA (more info)				Unavailable 👩
#27	1019-5314A 1	COVER ASSEMBLY, CYLINDER BLOC	CK (1 required p	per assembly)		
No Image Available	1019-5314A Replaced by 1	COVER ASSY O - Replaced by 1019-7465A 1 (more info)				Unavailable 👩
No Image Available	1019-7465A 1	COVER ASSY O NLA (more info)				Unavailable 👩
#28	22-52644	PLUG, CYLINDER BLOCK COVER (1	required per as	sembly)		
No Image Available	22-52644 OEM	22-52644 - Plug (more info)	MERCURY QUICK SILVER	\$0.85	\$0.85	7 in stock.
No Image Available	22-35268 OEM	22-35268 - Plug (more info)	MERCURY QUICKSILVER	\$1.85	\$1.85	ADD TO CART 2 in stock.
•	22-39072 Replaced by	PLUG O - Replaced by 22-39072 1 (more info)				Unavailable @
•	22-39072 1 OEM	22-39072 1 - Plug - Priced individually (more info)	MERCURY QUICKSILVER	\$6.10	\$6.10	Available to order: Usually ships within 8 days
#29	27-66358	GASKET, CYLINDER BLOCK COVER	(1 required per	assembly)		
(CiO) Q	27-66358 Replaced by	GASKET @5 O - Replaced by 27-78087 (more info)				Unavailable 👩
OO 0	27-78087 Replaced by	GASKET O - Replaced by 27-41382 (more info)				Unavailable 👩
660 6	27-41382 ОЕМ	27-41382 - Gasket (more info)	MERCURY QUICKSILVER	\$3.60	\$3.60	Available to order: Usually ships within 8 days
<u>(200</u>) 0	18-2837-9 Aftermarket	18-2837-9 - Gasket 27-78087 2-Pack (more info)	Sierra	\$8.26	\$5.94	2 in stock.
#30	10-69086	SCREW, CYL. BLOCK COVER TO CYL UNITED STATES 3801458 THRU 46 9043194 THRU 9150904 CANADA 7	91221 AUSTRA	LIA 8015315 T		

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
No Image Available	10-69086 OEM	10-69086 - Screw - Priced individually (more info)	MERCURY QUICKSILVER	\$0.40	\$0.40	ADD TO CART 10+ in stock.
No Image Available	10-21091 OEM	10-21091 - Screw, NLA (more info)	PERCURY	\$1.25	\$1.25	ADD TO CART 10+ in stock.
#30	10-76630	SCREW, CYL. BLOCK COVER TO CY UNITED STATES 4691222 AND UP UP CANADA 7095423 AND UP				50905 AND
€ ⊕	10-76630 OEM	10-76630 - Screw - Priced Individually (more info)	MERCURY QUICKSILVER	\$1.40	\$1.40	ADD TO CART
#32	27-46233	GASKET, BAFFLE PLATE (1 require	d per assembly)			
€	27-46233 Replaced by	GASKET @5 O - Replaced by 27-78035 (more info)				Unavailable 🧃
€	27-78035 OEM	27-78035 - Gasket - Priced individually (more info)	MERCURY QUICK SILVER	\$4.40	\$4.40	Available to order: Usually ships within 8 days
□ €	18-2836-9 Aftermarket	<u>18-2836-9 - Gasket 27-78035 2-Pack</u> (more info)	Sierra	\$8.13	\$6.45	2 in stock.
#33	46235	PLATE, BAFFLE - EXHAUST MANIF	OLD (1 required	per assembly)	
No Image Available	46235 Replaced by	PLATE O - Replaced by -78034 (more info)				Unavailable @
€	78034 OEM	78034 - Baffle Plate (more info)	MERCURY QUICKSILVER	\$24.17	\$24.17	Available to order: Usually ships within 8 days
#35	46172	COVER, EXHAUST MANIFOLD (1 re UNITED STATES 3801458 THRU 43 9043194 THRU 9115164 CANADA	397536 AUSTRAI	LIA 8015315 T	ΓHRU 803844	9 BELGIUM
No Image Available	46172 Replaced by	COVER O - Replaced by -74919 (more info)				Unavailable [
No Image Available	74919 Replaced by	COVER O - Replaced by -74919T (more info)				Unavailable [
No Image Available	74919T OEM	74919T - Cover, NLA (more info)	MERCURY QUICKSILVER	\$95.00	\$95.00	ADD TO CART
#35	74919	COVER, EXHAUST MANIFOLD (1 re UNITED STATES 4397537 AND UP UP CANADA 7076123 AND UP			BELGIUM 91	15165 AND
No Image Available	74919 Replaced by	COVER O - Replaced by -74919T (more info)				Unavailable 👩
No Image Available	74919T OEM	74919T - Cover, NLA (more info)	MERCURY QUICKSILVER	\$95.00	\$95.00	ADD TO CART
	10-28668	SCREW, BAFFLE PLATE AND MANI	FOLD COVER MO	UNTING (3/4	") (8 require	d per
#36		assembly)				
#36 •	10-28668 OEM	10-28668 - Screw - Priced Individually (more info)	PERCURY	\$1.20	\$1.20	ADD TO CART 10+ in stock.

Revise Search: Start Over > Different Engine Model > Different Serial Number Range > Different Component

YOU ARE HERE: MERCURY > 7.5 HP > 3801458 THRU 4851692 (USA) > CYLINDER BLOCK AND CRANKCASE ASSEMBLY

« Previous | Next »



Subscribe to the MarineEngine.com Newsletter

Periodically we'll send you Tech Tips, How-To's and Boating Information. Just enter your e-mail address and click Subscribe!

email address Subscribe

You can easily unsubscribe from the newsletter at any time.





HOME | CONTACT | SHIPPING | RETURNS | CART

Boat Engine PartsBoat Motor ManualsBoat Accessories

About Us | Terms of Use | Privacy Policy © 2015 MarineEngine.com, Inc. All rights reserved.



MarineEngine.com, 184 Jones Drive, Brandon, VT 05733 USA Phone: 802-247-4700 | Fax: 802-419-3055 | eMail: <u>info@marineengine.com</u>