


Parts for Mercury Marine 7.5 HP CARBURETOR AND CHOKE ASSEMBLY

Revise Search: Start Over > Different Engine Model > Different Serial Number Range > Different Component

YOU ARE HERE: MERCURY > 7.5 HP > 3801458 THRU 4851692 (USA) > CARBURETOR AND CHOKE ASSEMBLY

« Previous | Next »

Reference numbers in this diagram can be found in a light blue row below — scroll down to order. Each product listed is an <u>OEM</u> or <u>aftermarket</u> equivalent part. [<u>Example</u>]



Reference numbers in this diagram can be found in a light blue row below — scroll down to order. Each product listed is an $\underline{\mathsf{QEM}}$ or $\underline{\mathsf{aftermarket}}$ equivalent part. [$\underline{\mathsf{Example}}$]

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
#1	1364-4910A 1	CARBURETOR ASSEMBLY, COMP UNITED STATES 3801458 THRU 9043194 THRU 9068873 CANAD	4085864 AUSTRA	LIA 8015315	,	89 BELGIUM
No Image Available	1364-4910A 1 Replaced by	CARBURETOR O - Replaced by 1364-5645A 3 (more info)				Unavailable 🗿
No Image Available	1364-5645A 3 Replaced by	CARBURETOR O - Replaced by 1364-8783A 4 (more info)				Unavailable 👩

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
No Image Available	1364-8783A 4 Replaced by	CARBURETOR O - Replaced by 1364-8783A14 (more info)				Unavailable 🗿
No Image Available	1364-8783A14	CARBURETOR O NLA (more info)				Unavailable 🗿
#1	1364-5645A 3	CARBURETOR ASSEMBLY, COME UNITED STATES 4085865 THRU 9068874 THRU 9079488 CANAI	4131609 AUSTRA	LIA 8024690		339 BELGIUM
No Image Available	1364-5645A 3 Replaced by	CARBURETOR O - Replaced by 1364-8783A 4 (more info)				Unavailable 👩
No Image Available	1364-8783A 4 Replaced by	CARBURETOR O - Replaced by 1364-8783A14 (more info)				Unavailable 🗿
No Image Available	1364-8783A14	CARBURETOR O NLA (more info)				Unavailable 🗿
#1	1364-5645A 8	CARBURETOR ASSEMBLY, COMP UNITED STATES 4131610 THRU 9079489 THRU 9092863 CANAI	4248574 AUSTRA	LIA 8028840		714 BELGIUM
No Image Available	1364-5645A 8 Replaced by	CARBURETOR O - Replaced by 1364-5994 (more info)				Unavailable 🗿
No Image Available	1364-5994 Replaced by	CARBURETOR O - Replaced by 1364-6061 (more info)				Unavailable 🗿
No Image Available	1364-6061	CARBURETOR O NLA (more info).				Unavailable 🗿
#1	1364-5994	CARBURETOR ASSEMBLY, COMP UNITED STATES 4248575 THRU 9092864 THRU 9102613 CANAI	4314384 AUSTRA	LIA 8031715		569 BELGIUM
No Image Available	1364-5994 Replaced by	CARBURETOR O - Replaced by 1364-6061 (more info)				Unavailable 👩
No Image Available	1364-6061	CARBURETOR O NLA (more info)				Unavailable 🗿
#1	1364-6061	CARBURETOR ASSEMBLY, COMP UNITED STATES 4314385 THRU 9102614 THRU 9115164 CANAI	4397536 AUSTRA	LIA 8035570		149 BELGIUM
No Image Available	1364-6061	CARBURETOR O NLA (more info)				Unavailable 🗿
#1	1364-6289	CARBURETOR ASSEMBLY, COMPUNITED STATES 4397537 AND UP CANADA 7076123 AND UP				115165 AND
No Image Available	1364-6289 Replaced by	CARBURETOR O - Replaced by 1364-6649 (more info)				Unavailable 👩
No Image Available	1364-6649 Replaced by	CARBURETOR O - Replaced by 1364-8783A 4 (more info)				Unavailable 👩
No Image Available	1364-8783A 4 Replaced by	CARBURETOR O - Replaced by 1364-8783A14 (more info)				Unavailable 🗿
No Image Available	1364-8783A14	CARBURETOR O NLA (more info)				Unavailable 👩

3 of 7

Ref. No.		Part No.	Description	Manufacturer	List Price	Your Price	Order
No Image Available		32-63146 Replaced by	HOSE O - Replaced by 32-31583109 (more info)				Unavailable 🗿
No Image Available		32-31583109 Replaced by	HOSE O - Replaced by 32-99127109 (more info)				Unavailable 🗿
No Image Available ************************************		32-99127109 Replaced by	TUBING-57 INCH O - Replaced by 32-830756109 (more info)				Unavailable 🗿
	⊕,	32-830756109 Replaced by	HOSE-57 INCH O - Replaced by 32-8M0047428 (more info)				Unavailable 👩
\bigcirc	⊕(32-8M0047428 OEM	32-8M0047428 - Hose -57 INCH (more info)	MERCURY QUICKSILVER	\$43.90	\$37.59	1 in stock.
#3		54-68424	CLAMP, FUEL HOSE ATTACHING (2	required per as	sembly)		
No Image Available		54-68424 OEM	54-68424 - Clamp, NLA (more info)	MERCURY QUICKSILVER	\$3.50	\$3.50	10+ in stock.
#4		22-63981	FITTING, FUEL LINE TO ADAPTOR (UNITED STATES 3801458 THRU 43: 9043194 THRU 9102613 CANADA 7	14384 AUSTRAI	LIA 8015315	THRU 80355	69 BELGIUM
	⊕(22-63981 OEM	22-63981 - Fitting (more info)	PERCURY	\$43.20	\$36.99	10+ in stock.
#4		22-73705	FITTING, FUEL LINE TO ADAPTOR (UNITED STATES 4314385 AND UP UP CANADA 7065473 AND UP			BELGIUM 9	102614 AND
No Image Available		22-73705 Replaced by	FITTING O - Replaced by 22-98750 (more info)				Unavailable 🗿
No Image Available		22-98750 OEM	<u>22-98750 - Fitting, NLA</u> (more info)	MERCURY QUICKSILVER	\$22.50	\$22.50	10+ in stock.
#5		22833	ADAPTOR, CHECK UNIT (FUEL LINE) (1 required p	er assembly)		
1	⊕ ູ	22833 OEM	22833 - Adaptor (more info)	PERCURY QUICKSILVER	\$42.67	\$42.67	3 in stock.
#6		23069	STEM, CHECK UNIT ADAPTOR (1 re	quired per asse	mbly)		
	Đ	23069 OEM	23069 - Stem (more info)	PERCURY QUICKSILVER	\$22.40	\$19.18	10+ in stock.
#7		25-20415	"O" RING, ADAPTOR STEM (1 requi	red per assemb	oly)		
0	⊕(25-20415 OEM	25-20415 - O-ring - Priced individually (more info)	MERCURY QUICKSILVER	\$0.75	\$0.75	10+ in stock.
0	⊕,	25-16524 OEM	25-16524 - O-ring - Priced individually (more info)	MERCURY	\$1.10	\$1.10	ADD TO CART 10+ in stock.
0	⊕_	18-7421-9 Aftermarket	18-7421-9 - O-ring (PK5) 25-20415 (more info)	Sierra	\$8.45	\$8.45	1 in stock.
#8		24-23067	SPRING, ADAPTOR STEM (1 require	ed per assembly	')		
No Image Available		24-23067 Replaced by	SPRING O - Replaced by 24-23067T (more info)				Unavailable 👩
No Image Available		24-23067T OEM	24-23067T - Spring (more info)	PERCURY	\$2.40	\$2.40	Available to order:

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
" -	20100					Usually ships within 8 days
#9	30188	CUP WASHER, ADAPTOR (1 require	d per assembly)		
0	30188 OEM	30188 - Washer -cup - Priced individually (more info)	MERCURY QUICKSILVER	\$1.60	\$1.60	10+ in stock.
#10	10-37923	SCREW, ADAPTOR TO BOTTOM COW	/L (1 1/4") (1 ı	required per a	ssembly)	
No Image Available	10-37923 OEM	10-37923 - Screw, NLA (more info)	MERCURY	\$1.65	\$1.65	ADD TO CART 10+ in stock.
#11	65552	SCREEN, CARBURETOR (1 required	per assembly)			
THE P	65552	SCREEN O NLA (more info)				Unavailable 🗿
#12	10-20100	SCREW, SCREEN TO CARBURETOR (2 required per	assembly)		
No Image Available	10-20100 OEM	10-20100 - Screw - Priced individually (more info)	PERCURY	\$0.19	\$0.19	ADD TO CART 10+ in stock.
∂ ⊕	10-69022 OEM	10-69022 - Screw (more info)	MERCURY	\$0.80	\$0.80	ADD TO CART 10+ in stock.
#13	63980	KNOB, CHOKE (1 required per asser	mbly)			
No Image Available	63980 Replaced by	KNOB O - Replaced by -86381 (more info)				Unavailable 🗿
6	86381 OEM	86381 - Choke Knob, NLA (more info)	MERCURY QUICKSILVER	\$10.00	\$10.00	ADD TO CART 10+ in stock.
#14	11-73710	NUT, CHOKE CABLE TO BOTTOM CO	WL (1 required	per assembly)	
No Image Available	11-73710 OEM	11-73710 - Nut, NLA (more info)	MERCURY	\$1.35	\$1.35	2 in stock.
#15	63906	CABLE, CHOKE - SERIAL GROUP 5 (1 required per	assembly)		
No Image Available	63906 Replaced by	CHOKE CABLE O - Replaced by -72465 (more info)				Unavailable 🗿
•	72465 OEM	72465 - Choke Cable (more info)	MERCURY	\$38.50	\$32.96	Available to order: Usually ships within 8 days
#15	72465	CABLE, CHOKE (1 required per asse UNITED STATES 4131610 AND UP A UP CANADA 7050208 AND UP		8840 AND UP	BELGIUM 9	·
•	72465 OEM	72465 - Choke Cable (more info)	MERCURY QUICKSILVER	\$38.50	\$32.96	Available to order: Usually ships within 8 days
#16	10-45862	SCREW, CHOKE CABLE TO CARBURE UNITED STATES 3801458 THRU 439 9043194 THRU 9115164 CANADA 7	97536 AUSTRAI	LIA 8015315 T		49 BELGIUM
₽	10-45862 OEM	10-45862 - Screw - Priced Individually (more info)	MERCURY QUICKSILVER	\$1.00	\$1.00	ADD TO CART 10+ in stock.
#17	13-26996	LOCKWASHER, CHOKE CABLE SCREUNITED STATES 3801458 THRU 4399043194 THRU 9115164 CANADA 7	97536 AUSTRAI	LIA 8015315 T	THRU 80384	49 BELGIUM
No Image Available	13-26996 OEM	13-26996 - Lockwasher - Priced Individually (more info)	MERCURY QUICKSILVER	\$0.80	\$0.80	ADD TO CART 10+ in stock.

	Part No.	Description	Manufacturer	List Price	Your Price	Order
:17	12-56681	WASHER, CHOKE CABLE SCREW (1 UNITED STATES 3801458 THRU 43 9043194 THRU 9115164 CANADA	397536 AUSTRAL	IA 8015315 T	HRU 80384	49 BELGIUM
No Image Available	12-56681 OEM	12-56681 - Washer - Priced individually (more info)	MERCURY QUICK SILVER	\$1.40	\$1.40	Available to order: Usually ships within 8 days
18	23-63932	SPACER, CHOKE CABLE SCREW (1 UNITED STATES 3801458 THRU 4: 9043194 THRU 9102613 CANADA	314384 AUSTRAL	IA 8015315 T	HRU 80355	69 BELGIUM
No Image Available	23-63932	SPACER O NLA (more info)				Unavailable (
19	16-69036	STUD, CHOKE CABLE TO CARBURE UNITED STATES 4397537 AND UP UP CANADA 7076123 AND UP				L15165 AND
No Image Available	16-69036 OEM	16-69036 - Stud, NLA (more info)	MERCURY QUICK SILVER	\$2.00	\$2.00	4 in stock.
21	54-25231	CLIP, TRIGGER LEADS (1 required UNITED STATES 4397537 AND UP UP CANADA 7076123 AND UP		8450 AND UP	BELGIUM 91	L15165 AND
No Image Available	54-25231 OEM	54-25231 - Clip, NLA (more info)	WERCURY QUICK SILVER	\$4.50	\$4.50	9 in stock.
22	22789	"D" WASHER, TRIGGER LEAD CLIF UNITED STATES 4397537 AND UP UP CANADA 7076123 AND UP			BELGIUM 91	L15165 AND
No Image Available	22789 OEM	22789 - C Washer - Priced individually (more info)	MERCURY	\$0.25	\$0.25	ADD TO CART 10+ in stock.
s <u>(</u>	69205 OEM	69205 - C Washer (more info)	MERCURY QUICK SILVER	\$0.80	\$0.80	ADD TO CART 10+ in stock.
No Image Available	8M0084613	WASHER O (more info)				Unavailable (
:23	11-45076	NUT, CHOKE CABLE STUD (1 requi UNITED STATES 4397537 AND UP UP CANADA 7076123 AND UP			BELGIUM 91	L15165 AND
	11-45076 OEM	11-45076 - Nut - Priced Individually (more info)	MERCURY	\$1.20	\$1.20	ADD TO CART
No Image Available						
No Image Available	11-46887	NUT, CARBURETOR ATTACHING (2	required per ass	sembly)		
Available		NUT, CARBURETOR ATTACHING (2 NUT @15 O - Replaced by 11-20184 (more info)	? required per ass	sembly)		Unavailable (



Subscribe to the MarineEngine.com Newsletter

Periodically we'll send you Tech Tips, How-To's and Boating Information. Just enter your e-mail address and click Subscribe!

email address Subscribe

You can easily unsubscribe from the newsletter at any time.

Why Us & Reviews 📵 Boat Repair Forum 🚨 Video Gallery

HOME | CONTACT | SHIPPING | RETURNS | CART

Boat Engine PartsBoat Motor ManualsBoat Accessories

About Us | Terms of Use | Privacy Policy

© 2015 MarineEngine.com, Inc. All rights reserved.

MarineEngine.com, 184 Jones Drive, Brandon, VT 05733 USA

Phone: 802-247-4700 | Fax: 802-419-3055 | eMail: <u>info@marineengine.com</u>