


MarineEngine.com**PHONE ORDERS**


Monday - Friday

9:00 AM - 5:00 PM EST

Click for [TOLL-FREE](#) Number**BUY ONLINE****Flat Rate
Shipping****\$7.95**[see details](#)(800) 209-9624 | [HOME](#) | [CONTACT](#) | [SHIPPING](#) | [RETURNS](#) | [CART](#) **Part Number Search**Shop by engine/drive part number.
Original & matching parts for sale.**Manuals & Accessories**Shop by description, item number
or manufacturer's model number.[Why Us & Reviews](#)[Boat Repair Forum](#)[Video Gallery](#)**BOAT ENGINE PARTS****BOAT MOTOR MANUALS****BOAT ACCESSORIES**[Add to my favorites / bookmarks](#) [Print this page](#) **Parts for Mercury Marine 7.5 HP CLAMP BRACKET ASSEMBLY**Revise Search: [Start Over](#) > [Different Engine Model](#) > [Different Serial Number Range](#) > [Different Component](#)**YOU ARE HERE: MERCURY > 7.5 HP > 3801458 THRU 4851692 (USA) > CLAMP BRACKET ASSEMBLY**[« Previous](#) | [Next »](#)**Reference numbers in this diagram can be found in a light blue row below — scroll down to order.****Each product listed is an [OEM](#) or [aftermarket](#) equivalent part. [[Example](#)]**



Reference numbers in this diagram can be found in a light blue row below — scroll down to order.
Each product listed is an [OEM](#) or [aftermarket](#) equivalent part. [[Example](#)]

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
#1	1468-5407A 1	CLAMP BRACKET ASSEMBLY (PORT) (1 required per assembly) UNITED STATES 3801458 THRU 4131609 AUSTRALIA 8015315 THRU 8028839 BELGIUM 9043194 THRU 9079488 CANADA 7028598 THRU 7050207				
	1468-5407A 1 OEM	1468-5407A 1 - Clamp Bracket (more info)		\$20.65	\$20.65	 3 in stock. 
	1468-5570A 3 OEM	1468-5570A 3 - Clamp Bracket, NLA (more info)		\$85.00	\$85.00	 3 in stock. 

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
#2	1467-5406A 1	CLAMP BRACKET ASSEMBLY (STARBOARD) (1 required per assembly) UNITED STATES 3801458 THRU 4131609 AUSTRALIA 8015315 THRU 8028839 BELGIUM 9043194 THRU 9079488 CANADA 7028598 THRU 7050207				
	 1467-5406A Replaced by 1 ↓	CLAMP BRACKET O - Replaced by 1467-5571A 3 (more info)				Unavailable 
#3	 1467-5571A 3 OEM	1467-5571A 3 - Clamp Bracket, NLA (more info)		\$200.00	\$200.00	 1 in stock. 
	59170A 3	THUMB SCREW ASSEMBLY (2 required per assembly) UNITED STATES 3801458 THRU 4131609 AUSTRALIA 8015315 THRU 8028839 BELGIUM 9043194 THRU 9079488 CANADA 7028598 THRU 7050207				
#4	 59170A 3 OEM	59170A 3 - Thumb Screw Assembly (more info)		\$37.50	\$37.50	 5 in stock. 
	12-20214	WASHER, THUMB SCREW (2 required per assembly) UNITED STATES 3801458 THRU 4131609 AUSTRALIA 8015315 THRU 8028839 BELGIUM 9043194 THRU 9079488 CANADA 7028598 THRU 7050207				
#1	 12-20214 Replaced by ↓	WASHER @5 O - Replaced by 12-26227 (more info)				Unavailable 
	 12-26227 OEM	12-26227 - Washer, NLA (more info)		\$7.50	\$7.50	 10+ in stock. 
#2	1468-5570A 1	CLAMP BRACKET ASSEMBLY (PORT) (1 required per assembly) UNITED STATES 4131610 THRU 4314384 AUSTRALIA 8028840 THRU 8035569 BELGIUM 9079489 THRU 9102613 CANADA 7050208 THRU 7065472				
	 1468-5570A Replaced by 1 ↓	CLAMP BRACKET O - Replaced by 1468-5570A 2 (more info)				Unavailable 
#3	 1468-5570A Replaced by 2 ↓	CLAMP BRACKET O - Replaced by 1468-5570A 3 (more info)				Unavailable 
	 1468-5570A 3 OEM	1468-5570A 3 - Clamp Bracket, NLA (more info)		\$85.00	\$85.00	 3 in stock. 
#2	1467-5571A 1	CLAMP BRACKET ASSEMBLY (STARBOARD) (1 required per assembly) UNITED STATES 4131610 THRU 4314384 AUSTRALIA 8028840 THRU 8035569 BELGIUM 9079489 THRU 9102613 CANADA 7050208 THRU 7065472				
	 1467-5571A Replaced by 1 ↓	CLAMP BRACKET O - Replaced by 1467-5571A 2 (more info)				Unavailable 
#3	 1467-5571A Replaced by 2 ↓	CLAMP BRACKET O - Replaced by 1467-5571A 3 (more info)				Unavailable 
	 1467-5571A 3 OEM	1467-5571A 3 - Clamp Bracket, NLA (more info)		\$200.00	\$200.00	 1 in stock. 
#3	69157A 3	THUMB SCREW ASSEMBLY (2 required per assembly) UNITED STATES 4131610 THRU 4314384 AUSTRALIA 8028840 THRU 8035569 BELGIUM 9079489 THRU 9102613 CANADA 7050208 THRU 7065472				
	 69157A 3 Replaced by ↓	THUMB SCREW ASSY O - Replaced by -74159A 3 (more info)				Unavailable 
#3	 74159A 3 Replaced by ↓	THUMB SCREW ASSY O - Replaced by 10-77190A 3 (more info)				Unavailable 
	 10-77190A 3	SCREW ASSY-THUMB O NLA (more info)				Unavailable 

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
#1	1468-5570A 2	CLAMP BRACKET ASSEMBLY (PORT) (1 required per assembly)				
	1468-5570A 2 Replaced by ↓	CLAMP BRACKET O - Replaced by 1468-5570A 3 (more info)				Unavailable 
	1468-5570A 3 OEM	1468-5570A 3 - Clamp Bracket, NLA (more info)		\$85.00	\$85.00	 3 in stock. 
#2	1467-5571A 2	CLAMP BRACKET ASSEMBLY (STARBOARD) (1 required per assembly) UNITED STATES 4314385 AND UP AUSTRALIA 8035570 AND UP BELGIUM 9102614 AND UP CANADA 7065473 AND UP				
	1467-5571A 2 Replaced by ↓	CLAMP BRACKET O - Replaced by 1467-5571A 3 (more info)				Unavailable 
	1467-5571A 3 OEM	1467-5571A 3 - Clamp Bracket, NLA (more info)		\$200.00	\$200.00	 1 in stock. 
#3	74159A 3	THUMB SCREW ASSEMBLY (2 required per assembly)				
	74159A 3 Replaced by ↓	THUMB SCREW ASSY O - Replaced by 10-77190A 3 (more info)				Unavailable 
	10-77190A 3	SCREW ASSY-THUMB O NLA (more info)				Unavailable 
#5	12-52864	WASHER, TILT TUBE - CLAMP TO SWIVEL BRACKET (2 required per assembly) UNITED STATES 3801458 THRU 4314384 AUSTRALIA 8015315 THRU 8035569 BELGIUM 9043194 THRU 9102613 CANADA 7028598 THRU 7065472				
	12-52864 OEM	12-52864 - Washer, NLA (more info)		\$2.50	\$2.50	 10+ in stock. 
#6	45757	TILT TUBE, CLAMP TO SWIVEL BRACKET (1 required per assembly) UNITED STATES 3801458 THRU 4314384 AUSTRALIA 8015315 THRU 8035569 BELGIUM 9043194 THRU 9102613 CANADA 7028598 THRU 7065472				
	45757 OEM	45757 - Tilt Tube, NLA (more info)		\$68.75	\$68.75	 8 in stock. 
#5	12-71421	WASHER, TILT TUBE - CLAMP TO SWIVEL BRACKET (2 required per assembly) UNITED STATES 4314385 AND UP AUSTRALIA 8035570 AND UP BELGIUM 9102614 AND UP CANADA 7065473 AND UP				
	12-71421 OEM	12-71421 - Washer - Priced individually (more info)		\$1.40	\$1.40	 1 in stock. 
#6	74250	TILT TUBE, CLAMP TO SWIVEL BRACKET (1 required per assembly) UNITED STATES 4314385 AND UP AUSTRALIA 8035570 AND UP BELGIUM 9102614 AND UP CANADA 7065473 AND UP				
	74250 OEM	74250 - Tilt Tube (more info)		\$18.85	\$18.85	 1 in stock. 
	96962 OEM	96962 - Tilt Tube, NLA (more info)		\$25.00	\$25.00	 6 in stock. 
#7	19-39333	PLUG, TILT TUBE (2 required per assembly) UNITED STATES 4314385 AND UP AUSTRALIA 8035570 AND UP BELGIUM 9102614 AND UP CANADA 7065473 AND UP				
	19-39333 OEM	19-39333 - Plug (more info)		\$2.30	\$2.30	 Available to order: Usually ships within 8 days 
#8	54-30954	CLIP, SAFETY CHAIN - TILT TUBE (1 required per assembly)				

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
#9	 54-30954 OEM	54-30954 - Clip (more info)		\$6.00	\$6.00	 Available to order: Usually ships within 8 days 
	11-56041	NUT, TILT TUBE FASTENING (2 required per assembly)				
	 11-56041 Replaced by ↓	NUT @2 O - Replaced by 11-30499 (more info)				Unavailable 
#10	 11-30499 OEM	11-30499 - Nut - Priced Individually (more info)		\$1.80	\$1.80	 5 in stock. 
	11-858869 OEM	11-858869 - Nut - Priced individually (more info)		\$3.20	\$3.20	 Available to order: Usually ships within 8 days 
	65475	HANDLE, CARRYING (1 required per assembly) UNITED STATES 3801458 THRU 4314384 AUSTRALIA 8015315 THRU 8035569 BELGIUM 9043194 THRU 9102613 CANADA 7028598 THRU 7065472				
#11	 65475 OEM	65475 - Handle, NLA (more info)		\$5.50	\$5.50	 6 in stock. 
	16-59622	STUD, CLAMP BRACKET (1 required per assembly) UNITED STATES 3801458 THRU 4314384 AUSTRALIA 8015315 THRU 8035569 BELGIUM 9043194 THRU 9102613 CANADA 7028598 THRU 7065472				
	 16-59622	STUD O NLA (more info)				Unavailable 
#10	71420	HANDLE, CARRYING (1 required per assembly) UNITED STATES 4314385 AND UP AUSTRALIA 8035570 AND UP BELGIUM 9102614 AND UP CANADA 7065473 AND UP				
	 71420	HANDLE O NLA (more info) Replaces OEM #3854260				Unavailable 
	16-71417	STUD, CLAMP BRACKET (1 required per assembly) UNITED STATES 4314385 AND UP AUSTRALIA 8035570 AND UP BELGIUM 9102614 AND UP CANADA 7065473 AND UP				
#12	 16-71417 OEM	16-71417 - Stud, NLA (more info)		\$19.00	\$19.00	 8 in stock. 
	13-26992	LOCKWASHER, CLAMP BRACKET STUD (2 required per assembly)				
	 13-26992 OEM	13-26992 - Lockwasher - Priced Individually (more info)		\$0.80	\$0.80	 10+ in stock. 
#13	11-29598	NUT, CLAMP BRACKET STUD (2 required per assembly)				
	 11-29598 OEM	11-29598 - Nut - Priced Individually (more info)		\$1.80	\$1.80	 10+ in stock. 
	24-62143	SPRING, TILT LOCK PIN (1 required per assembly)				
#15	 24-62143 OEM	24-62143 - Spring - Priced individually (more info)		\$4.00	\$4.00	 10+ in stock. 
	17-55952A 1	TILT LOCK PIN ASSEMBLY (1 required per assembly) UNITED STATES 3801458 THRU 4314384 AUSTRALIA 8015315 THRU 8035569 BELGIUM 9043194 THRU 9102613 CANADA 7028598 THRU 7065472				
	 17-55952A 1 OEM	17-55952A 1 - Pin - Lock (more info)		\$37.90	\$32.46	 1 in stock. 
#15	17-71418A 2	TILT LOCK PIN ASSEMBLY (1 required per assembly) UNITED STATES 4314385 AND UP AUSTRALIA 8035570 AND UP BELGIUM 9102614 AND UP CANADA 7065473 AND UP				

Ref. No.	Part No.	Description	Manufacturer	List Price	Your Price	Order
	 17-71418A 2 OEM	17-71418A 2 - Pin (more info)		\$38.30	\$32.80	 ADD TO CART 4 in stock. 
#16	10-67982	BOLT, CLAMP BRACKET TO BOAT (2 required per assembly)				
	10-67982 OEM	10-67982 - Screw, NLA (more info)		\$3.00	\$3.00	 ADD TO CART 10+ in stock. 
#17	12-67983	WASHER, CLAMP BRACKET SCREW (2 required per assembly)				
	12-67983 OEM	12-67983 - Washer (more info)		\$2.00	\$2.00	 ADD TO CART 8 in stock. 
#18	11-56374	NUT, CLAMP BRACKET SCREW (2 required per assembly)				
	11-56374 Replaced by ↓	NUT @2 O - Replaced by 11-826709 8 (more info)				Unavailable 
	11-826709 8 OEM	11-826709 8 - Nut - Priced individually (more info)		\$4.60	\$4.60	 ADD TO CART Available to order: Usually ships within 8 days 

Revise Search: [Start Over](#) > [Different Engine Model](#) > [Different Serial Number Range](#) > [Different Component](#)

YOU ARE HERE: MERCURY > 7.5 HP > 3801458 THRU 4851692 (USA) > **CLAMP BRACKET ASSEMBLY**

« [Previous](#) | [Next](#) »



Subscribe to the MarineEngine.com Newsletter

Periodically we'll send you Tech Tips, How-To's and Boating Information.
Just enter your e-mail address and click Subscribe!

email address

You can easily unsubscribe from the newsletter at any time.

 [Why Us & Reviews](#)  [Boat Repair Forum](#)  [Video Gallery](#)

[HOME](#) | [CONTACT](#) | [SHIPPING](#) | [RETURNS](#) | [CART](#)

[Boat Engine Parts](#)[Boat Motor Manuals](#)[Boat Accessories](#)

[About Us](#) | [Terms of Use](#) | [Privacy Policy](#)

© 2015 MarineEngine.com, Inc. All rights reserved.



MarineEngine.com, 184 Jones Drive, Brandon, VT 05733 USA

Phone: 802-247-4700 | Fax: 802-419-3055 | eMail: info@marineengine.com